

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III21000837/T1QF3E2-1

**Date:** 02/08/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SLL6826P **Insured Vehicle No :** SLQ774T  
Date of Loss: 17/01/2021 Nature of Claim: TP Claim No: MFL2021D0000338

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL6826P**  
Make & Model: VOLKSWAGEN NEW GOLF, 1.4 AT 5K13G5 (A) Engine No: CAX515447  
Reg. Date: 25/05/2010 (Man. Year: 2010) Chassis No: WVVZZZ1KZAW346378  
Colour: White Odometer: 224043 km  
Engine Capacity: 1390 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18  
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm  
Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,462.13	7,641.37	2,820.76	26.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,381.50	1,985.00	396.50	16.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,843.63</b>	<b>9,626.37</b>	<b>3,217.26</b>	<b>25.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,700.00</b>		
<b>(S\$)</b>	12,843.63	7,700.00	5,143.63	40.05
<b>+ GST 7.00/7.00% (S\$)</b>	899.05	539.00	360.05	40.05
<b>Nett Amount (S\$)</b>	<b>13,742.68</b>	<b>8,239.00</b>	<b>5,503.68</b>	<b>40.05</b>

### INSPECTION

Date of Assignment: 21/07/2021  
Date Inspected: 19/01/2021 Inspected At: Garage 13 Pte Ltd (HQ)  
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46  
Singapore 415875  
Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 02 Aug 2021)

**Parts:** 144    VOLKSWAGEN NEW GOLF 1.4 AT 5K13G5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLL6826P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Crushed	1,854.00 FL	*1,854.00 FL
2	2		*TAIL GATE REFLECTOR	O/S Cracked / N/S Split	511.30 FL	*511.30 FL
3	1		*TAIL GATE TOP LOCK	Bent-in / Jammed	224.00 FL	*192.30 FL
4	1		*TAIL GATE SHOCK ABSORBER	Not Necessary	337.08 FL	*- FL
5	1		*TAIL GATE OUTER HANDLE	Cracked	214.00 FL	*214.00 FL
6	1		*TAIL GATE TOP INNER GARNISH	Damaged	185.40 FL	*185.40 FL
7	1		*TAIL GATE WEATHER STRIP	Ripped / Necessary	253.00 FL	*253.00 FL
8	1		*TAIL GATE INNER TRIM BOARD	Deformed	428.70 FL	*350.40 FL
9	2		*SET REAR NUMBER PLATE LAMP	Cracked	130.00 FL	*130.00 FL
10	1		*REAR BUMPER	Deformed	1,185.40 FL	*1,088.40 FL
11	1		*REAR BUMPER INNER CENTER GUIDE RAIL	Cracked	145.80 FL	*145.80 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	76.00 FL	*76.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	584.00 FL	*494.70 FL
14	1		*REAR BUMPER LOWER LID	Damaged	485.80 FL	*400.90 FL
15	2		*REAR BUMPER REFLECTOR	Holder Broken	136.00 FL	*136.00 FL
16	2		*TAIL LAMP	N/S Holder Broken / O/S Cut	712.00 FL	*712.00 FL
17	1		*REAR END PANEL	Multiple dented	918.00 FL	*755.10 FL
18	2		*REAR BUMPER REVERSE SENSOR	Malfunction	430.00 FL	*430.00 FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	202.30 FL	*- FL
20	1		*REAR EXHAUST PIPE	Repair	624.50 FL	*- FL
21	1		*DRIVER CENTRE CONSOLE HOUSING ASSY	Not Necessary	351.20 FL	*- FL
22	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*REAR NUMBER PLATE	Cracked	120.00 FS	*45.00 FS
24	1		*REVERSE CAMERA	Malfunction	342.50 FS	*280.00 FS
25	1		*AUDIO AMPLIFIER (5mo.0353.570.B)	Not Necessary	800.00 FS	*- FS
26	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS
27	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,460.98</b>	<b>8,434.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	998.85	792.93
<b>Total Parts (\$)</b>	<b>10,462.13</b>	<b>7,641.37</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	855.00	800.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	850.00	800.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	40.00
4	REMOVE AND REFIX TAILGATE REAR WINDSCREEN GLASS. (2-MAN JOB)	New	157.50	120.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	30.00
6	REMOVE AND REPLACE REAR REVERSE CAMERA & CONDUCT DISTANCE SAFETY SETTING	New	76.50	30.00
7	TRANSFER OF EXISTING FRONT DOOR MECHANISM TO NEW DOOR	New	90.00	60.00
8	REMOVE AND REBUILT REAR EXHAUST SYSTEM	New	45.00	45.00
9	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS	New	45.00	30.00
10	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	36.00	30.00
11	SPECIALIST CHARGES - COMMISSIOING OF AUDIO AMPLIFIER SYSTEM	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,381.50</b>	<b>1,985.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >