

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8745U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | BENT | 600.00 | 600.00 |
| 1 | TAIL GATE | TO REPAIR SEE LABOUR | 1,192.00 | - |
| 4 | REAR BUMPER CLIPS @\$5.10 | NECESSARY | 20.40 | 20.40 |
| 1 | RH REAR FENDER | TO REPAIR SEE LABOUR | 1,172.00 | - |
| 1 | LH REAR FENDER | TO REPAIR SEE LABOUR | 1,172.00 | - |
| 1 | REAR BUMPER BEAM | BENT | 300.00 | 300.00 |
| 1 | REAR TOW COVER | SERVICEABLE | 16.00 | - |
| 1 | REAR EXHAUST | TO REPAIR SEE LABOUR | 601.80 | - |
| 1 | REAR END PANEL | BENT | 450.00 | 450.00 |
| | LESS 20% DISCOUNT | | -1,104.84 | -274.08 |
| | | | 4,419.36 | 1,096.32 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR REVERSE SENSOR (SN) | SHORTED | 320.00 | 200.00 |
| | | | 320.00 | 200.00 |
| | <u>LABOUR</u> | | _ | |
| | ANTI-RUST COATING. | NOT NECESSARY | 160.00 | - |
| | PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF TAIL GATE, RH REAR FENDER, LH REAR FENDER AND REAR EXHAUST. | | 2,000.00 | 600.00 |
| | PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES. | | 2,000.00 | 660.00 |
| | PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING. | | 150.00 | 20.00 |
| | REMOVE AND REPLACEMENT OF EXHAUST PIPE TO FACILITATE REPAIR. | NOT NECESSARY | 250.00 | - |

Report Ref No. CS/AGI21007776/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|----------------------|---------------|-------------------------------|-------------------|
| | REALIGN OF EXHAUST. | NOT NECESSARY | 150.00 | - |
| | | | 4,710.00 | 1,280.00 |
| | GRAND TOTAL | | 9,449.36 | 2,576.32 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 2,050.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS/AGI21007776/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser