

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007791/UGA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700059828
Claimant Vehicle No :	SKQ8504R	Insured Vehicle No :	SLS7790P
Date of Loss:	16/07/2021	Nature of Claim:	TP
		Claim No:	1006585827SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ8504R	Engine No:	1AZE059520
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107016976
Reg. Date:	18/09/2007 (Man. Year: 2007)	Odometer:	249906 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,458.92	1,531.67	3,927.25	71.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,010.00	1,000.00	49.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,468.92	2,541.67	4,927.25	65.97
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	7,468.92	2,000.00	5,468.92	73.22
+ GST 7.00/7.00% (S\$)	522.82	140.00	382.82	73.22
Nett Amount (S\$)	7,991.74	2,140.00	5,851.74	73.22
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
Nett Liability (S\$)		2,354.00		

INSPECTION

Date of Assignment:	21/07/2021		
Date Inspected:	21/07/2021	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S FRONT FENDER	Badly Dented	810.00 FL	*810.00 FL
2	1		*N/S FRONT LPWER ARM	Not Necessary	235.90 FL	*- FL
3	1		*N/S FRONT FENDER INNER COWLING	Distorted	153.20 FL	*153.20 FL
4	6		*N/S FRONT FENDER INNER COWLING CLIPS	Necessary	27.00 FL	*27.00 FL
5	1		*N/S HEADLAMP	Not Necessary	2,676.30 FL	*- FL
6	1		*N/S FRONT DOOR	Not Necessary	1,280.00 FL	*- FL
7	1		*N/S FRONT DOOR PROTECTOR	Not Necessary	115.00 FL	*- FL
8	1		*N/S FRONT ABSORBER	Not Necessary	435.80 FL	*- FL
9	1		*FRONT BUMPER	Deformed / Torn	518.70 FL	*518.70 FL
10	1		*N/S FRONT RIM	Cut	450.00 FS	*400.00 FS
11	1		*N/S FRONT TYRE	Serviceable	320.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	7,021.90 1,908.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,562.98 377.23
					Total Parts (\$\$)	5,458.92 1,531.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	650.00	300.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	750.00	600.00
3	TO DROP FRONT N/S SUSPENSION UNDERCARRIAGE PARTS ,REMOVE AND RENEWAL OF THE NECESSARY PARTS ,TO PERFORM FINAL CHECKING AND TESTING	New	150.00	0.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
6	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	120.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	30.00
8	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	50.00	0.00
Gross Labour Cost (\$\$)			2,010.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >