

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21007796/ETF3E2

Date: 17/08/2021

REFERENCE

Insured/Claimant:	EUGENE SEAH WEE JIN	Policy No:	1900114470		
Date of Loss:	21/07/2021	Nature of Claim:	OD	Claim No:	2011287764SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH9923M	Engine No:	G4FGKH744163
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5049704
Reg. Date:	28/06/2019 (Man. Year: 2019)	Odometer:	16560 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$79,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,045.60	2,642.40	4,403.20	62.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	3,430.00	1,710.00	33.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,185.60	6,072.40	6,113.20	50.17
+ GST 7.00/7.00% (S\$)	852.99	425.07	427.92	50.17
Nett Amount (S\$)	13,038.59	6,497.47	6,541.12	50.17

INSPECTION

Date of Assignment:	21/07/2021		
Date Inspected:	21/07/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*COVER-RR BUMPER	Dented	651.00 FL	*651.00 FL
3	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
4	1		*COVER-RR BUMPER UNDER, LH	Not Necessary	33.00 FL	*- FL
5	1		*COVER-RR BUMPER FOG LAMP, LH	Cut	88.00 FL	*88.00 FL
6	1		*COVER-RR BUMPER FOG LAMP, RH	Not Necessary	88.00 FL	*- FL
7	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
8	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
9	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
10	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
11	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
12	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
13	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
14	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
15	1		*BRACKET-RR BEAM LWR, CTR	Crushed	6.00 FL	*6.00 FL
16	2		*BRACKET-RR BEAM LWR MTG	Crushed	6.00 FL	*12.00 FL
17	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
18	1		*COVER-RR BUMPER UNDER, RH	Not Necessary	33.00 FL	*- FL
19	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
20	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FL	*- FL
21	4		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	652.00 FL	*- FL
22	10		*CLIP	Necessary	10.00 FL	*10.00 FL
23	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
24	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	97.00 FL	*- FL
25	1		*HINGE ASSY-TRUNK LID, RH	Not Necessary	97.00 FL	*- FL
26	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
27	1		*TRIM ASSY-RR TRANSVERSE	Crushed	41.00 FL	*41.00 FL
28	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	211.00 FL	*- FL
29	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
30	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 FL	*- FL
31	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
32	1		*TRIM ASSY-TRUNK LID	Not Necessary	202.00 FL	*- FL
33	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
34	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
35	1		*LAMP ASSY-REAR COMB INSIDE, LH	Not Necessary	608.00 FL	*- FL
36	1		*LAMP ASSY-REAR COMB INSIDE, RH	Not Necessary	608.00 FL	*- FL
37	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Not Necessary	675.00 FL	*- FL
38	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Not Necessary	675.00 FL	*- FL
39	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,802.00	3,298.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,756.40	655.60
Total Parts (\$\$)	7,045.60	2,642.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER, BOOTLID & RR END PNL. REPAIR RR FLR PNL, LHR FENDER & RHR FENDER	New	2,400.00	1,400.00
2	RESPRAY RR BUMPER, RR END PNL, BOOTLID, RR FLR PNL, LHR FENDER & RHR FENDER	New	2,100.00	1,440.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
8	REMOVE & REFIT REVERSE SENSOR	New	80.00	80.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
10	SUPPLY BODY PNL SEALANT	New	40.00	40.00
11	SUPPLY C&C BADGE	New	40.00	40.00
Gross Labour Cost (S\$)			5,140.00	3,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >