

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007800/UGS3Q2
Date: 05/10/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SLA9893H

Date of Loss: 15/07/2021

Policy No:

Insured Vehicle No :

SME3646L

Nature of Claim:

TP

Claim No:

3469145015SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLA9893H**

Make & Model: AUDI A4, 1.8 TFSI (A)

Reg. Date: 26/01/2016 (Man. Year: 2015)

Colour: Blue

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CVN001394

Chassis No: WAUZZZF49GA012726

Odometer: 39039 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Front Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Tyre Size:

225/50 R17

Rear Left Side:

Michelin 7 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,823.21	1,899.90	923.31	32.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	700.00	200.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,723.21	2,599.90	1,123.31	30.17
Approved Total (Overridden) (S\$)		2,050.00		

Nett Amount (S\$)	3,723.21	2,050.00	1,673.21	44.94
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
Nett Liability (S\$)		2,170.00		

INSPECTION

Date of Assignment: 21/07/2021

Date Inspected: 21/07/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Soc Leon Motor Works (Kaki Bukit)
 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS	New	300.00	200.00
2	SPRAYPAINTING	New	600.00	500.00
Gross Labour Cost (S\$)			900.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >