

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007802/R1TCN2**Date:** 30/09/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00120342000

Claimant Vehicle No : SGN1012C**Insured Vehicle No :** SLS9664H

Date of Loss: 18/07/2021

Nature of Claim: TP

Claim No: SNM21D203995/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGN1012C**

Make & Model: KIA CARENS, 1.7 D SUNROOF (A)

Engine No: D4FDGH113171

Reg. Date: 15/09/2016 (Man. Year: 2016)

Chassis No: KNAHU815VG7164359

Colour: Grey

Odometer: 119102 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size: 225/45R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,816.00	952.00	864.00	47.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,570.00	2,830.00	2,740.00	49.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,386.00	3,782.00	3,604.00	48.80
+ GST 7.00/7.00% (S\$)	517.02	264.74	252.28	48.80
Nett Amount (S\$)	7,903.02	4,046.74	3,856.28	48.80

INSPECTION

Date of Assignment: 21/07/2021

Date Inspected: 27/08/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Sep 2021)
Parts:	143	KIA CARENS 1.7 D SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN1012C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER,UPR	Deformed	576.00 FS	*576.00 FS
2	1		*COVER-RR BUMPER,LWR	Cracked	211.00 FS	*211.00 FS
3	1		*BEAM-RR BUMPER	Serviceable	367.00 FS	*- FS
4	1		*BRACKET ASSY-RR BUMPER SIDE,LH	Serviceable	25.00 FS	*- FS
5	2		*ULTRASONIC SENSOR ASSY-P.A.S	Serviceable	324.00 FS	*- FS
6	4		*HOLDER-BACK WARING SYSTEM INR	Not Necessary	16.00 FS	*- FS
7	4		*HOLDER-BACK WARING SYSTEM OTR	Not Necessary	16.00 FS	*- FS
8	1		*LAMP ASSY-REAR FOG,LH	Serviceable	116.00 FS	*- FS
9	1		*EMBLEM-CARENS	Necessary	36.00 FS	*36.00 FS
10	1		*EMBLEM-CRDI	Necessary	29.00 FS	*29.00 FS
11	1		*SUNDRIES	Necessary	50.00 FS	*50.00 FS
12	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	1,816.00	952.00
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER & RR BUMPER BODY KIT.REPAIR RR END PNL & TAILGATE	New	2,560.00	1,280.00
2	RESPRAY RR BUMPER,RR END PNL,TAILGATE & RR BUMPER BODY KIT	New	2,200.00	1,100.00
3	REMOVE & REFIT RR FLR BOARD,TRIM & CARPET	New	300.00	0.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	50.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
6	REMOVE & REFIT REVERSE SENSOR	New	100.00	80.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	60.00
Gross Labour Cost (S\$)			5,570.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >