



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 756Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (SN)	TO REPAIR SEE LABOUR	894.00	-
1	FRONT BUMPER CONNECTING PIECE (SN)	NOT NECESSARY	148.00	-
1	FRONT BUMPER FIXING PARTS (SN)	NOT NECESSARY	347.00	-
1	FRONT BUMPER GRILLE CENTER (SN)	NOT NECESSARY	407.00	-
1	FRONT BUMPER TRIM CENTER (SN)	NOT NECESSARY	356.00	-
1	FRONT BUMPER AIR GUIDE GRILLE - RH (SN)	CUT	342.00	342.00
1	FRONT BUMPER AIR GUIDE GRILLE TRIM - RH (SN)	NOT NECESSARY	223.00	-
1	FRONT BUMPER AIR GUIDE GRILLE END CAP - RH (SN)	NOT NECESSARY	113.00	-
1	FRONT BUMPER SPOILER (SN)	NOT NECESSARY	536.00	-
1	FRONT BUMPER CLOSING ELEMENT (SN)	NOT NECESSARY	156.00	-
1	FRONT WHEEL SPOILER - RH (SN)	NOT NECESSARY	34.00	-
1	FRONT BUMPER ADAPTOR - RH (SN)	NOT NECESSARY	42.00	-
1	FRONT WHEEL HOUSING LINER TRIM - RH (SN)	NOT NECESSARY	33.00	-
1	RADIATOR GRILLE (SN)	CUT	1,411.00	1,411.00
1	RADIATOR GRILLE STRIKER PLATE (SN)	* CHECK	124.00	-
1	FRONT BUMPER REINFORCEMENT BEAM (SN)	NOT NECESSARY	723.00	-
1	REINFORCEMENT BEAM FOAM FILLER PIECE (SN)	NOT NECESSARY	78.00	-
1	FRONT BUMPER GUIDE SECTION RH (SN)	NOT NECESSARY	36.00	-
1	FRONT BUMPER TOP COVER (SN)	NOT NECESSARY	100.00	-
1	"CAUTION" STICKER (SN)	NOT NECESSARY	14.00	-
1	AIRCOND STICKER (SN)	NOT NECESSARY	8.00	-
1	HEADLIGHT MOUNTING - RH (SN)	NOT NECESSARY	118.00	-
1	LED HEADLIGHT - RH (SN)	NOT NECESSARY	4,915.00	-
1	LIFT CYLINDER - RH (SN)	NOT NECESSARY	142.00	-
1	LIFTY CYLINDER HOSE (SN)	NOT NECESSARY	182.00	-
2	FRONT WHEEL ARCH COVER - LH / RH (SN)	NECESSARY	848.00	848.00
1	RADIATOR AIR GUIDE - RH (SN)	NOT NECESSARY	38.00	-
1	RADIATOR SEAL - RH OUTER (SN)	NOT NECESSARY	7.00	-
1	RADIATOR AIR GUIDE - RH UPPER CENTRE (SN)	NOT NECESSARY	22.00	-
1	FRONT NO PLATE (SN)	NECESSARY	60.00	60.00

Report Ref No. CS/SMR21007805/Aqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	* CHECK	300.00	-
			12,757.00	2,661.00
	LABOUR			
	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.		360.00	360.00
	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	NOT NECESSARY	400.00	-
	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,200.00	800.00
	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.		3,000.00	1,400.00
	TO SUPPLY FILM AND RE-WRAP RADIATOR GRILLE (NPA).	NOT NECESSARY	-	-
TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00	
			5,152.00	2,752.00
GRAND TOTAL			17,909.00	5,413.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$424.00 NETT)				5,413.00

Report Ref No. CS/SMR21007805/Aqy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.