

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21007807/ATF3N2**Date:** 14/09/2021REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLN2974K **Insured Vehicle No :** SLX3308A

Date of Loss: 16/07/2021 Nature of Claim: TP Claim No: DMPC2100231H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN2974K**

Make & Model: BMW 640I, 3.0 (A) Engine No: 03857754N55B30A

Reg. Date: 09/06/2011 (Man. Year: 2011) Chassis No: WBALW72080C582653

Colour: Blue Odometer: 54386 km

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/55R20 Rear Tyre Size: 275/55R20

Front Left Side: RADAR 6 mm Rear Left Side: RADAR 6 mm

Front Right Side: RADAR 6 mm Rear Right Side: RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,342.00	3,224.40	4,117.60	56.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	970.00	1,150.00	54.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,462.00	4,194.40	5,267.60	55.67
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	9,462.00	3,300.00	6,162.00	65.12

INSPECTION

Date of Assignment: 21/07/2021

Date Inspected: 23/07/2021 Inspected At: 2020 Spray Painting Pte Ltd (HQ)
53 UBI AVE 1, #05-15 PAYA UBI INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Sep 2021)	
Parts:	N/A	BMW 640I 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN2974K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,088.00 F	*2,088.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	250.00 F	*250.00 FL
3	1		*REAR BUMPER INNER GUIDE (CENTRE)	Cracked	161.00 F	*161.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	751.00 F	*- FL
5	1		*REAR BUMPER UNDER COVER	Cracked	145.00 F	*145.00 FL
6	2		*REVERSE SENSOR	Damaged	560.00 F	*560.00 FL
7	1		*REAR END PANEL	Repair	885.00 F	*- FL
8	1		*REAR END PANEL TOP GARNISH	Cracked	212.00 F	*212.00 FL
9	2		*TAILLAMP	Not Necessary	1,410.00 F	*- FL
10	1		*BOOTLID LOCK	Not Necessary	485.00 F	*- FL
11	1		*BOOTLID WEATHERSTRIPE	Not Necessary	245.00 F	*- FL
12	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
13	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
14	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
15	1		*REAR BUMPER UNDER COVER CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,342.00	3,566.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	341.60
Total Parts (\$\$)	7,342.00	3,224.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	800.00	500.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	120.00	60.00
5	TO SPRAY TUFF COAT	New	150.00	40.00
6	TO REMOVE UPHOLSTERY	New	150.00	40.00
Gross Labour Cost (\$\$)			2,120.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >