

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007811/UGA3Q2**Date:** 20/05/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FX8383U**Insured Vehicle No :** SMA8991C

Date of Loss: 15/07/2021

Nature of Claim: TP

Claim No: 9089636579SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FX8383U**

Make & Model: YAMAHA FZ16, 153cc (M)

Engine No: 21CD007365

Reg. Date: 27/08/2012 (Man. Year: 2012)

Chassis No: ME121C0D7C2008330

Colour: Grey

Odometer: 0 km

Engine Capacity: 153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100-80 -17

Rear Tyre Size: 130-70-17

Front Left Side: Dunlop 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,964.90	996.50	2,968.40	74.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	310.00	690.00	69.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,964.90	1,306.50	3,658.40	73.69
Approved Total (Overridden) (S\$)		1,000.00		
Nett Amount (S\$)	4,964.90	1,000.00	3,964.90	79.86
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,100.00		

INSPECTION

Date of Assignment: 21/07/2021

Date Inspected: 21/07/2021 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Repair	105.00 FL	*- FL
2	2		*FORK INNER TUBES	Serviceable	480.00 FL	*- FL
3	1		*FORK OUTER TUBES	N/S Damaged	500.00 FL	*220.00 FL
4	1		*FORK UNDER BRACKET	Not Necessary	265.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Scratched	55.00 FL	*42.00 FL
6	1		*FRONT RIM BEARING	Not Necessary	45.00 FL	*- FL
7	1		*FRONT BRAKE DISC	Not Necessary	185.00 FL	*- FL
8	1		*HEADLAMP	Not Necessary	520.00 FL	*- FL
9	1		*HANDLE-BAR	Not Necessary	150.00 FL	*- FL
10	1		*HANDLE-BAR BALANCER	Not Necessary	68.00 FL	*- FL
11	1		*SET HAND GRIP	Not Necessary	85.00 FL	*- FL
12	1		*FRONT SIDE LOWER COVER	Cracked	70.00 FL	*70.00 FL
13	1		*CLUTCH LEVER	Not Necessary	35.00 FL	*- FL
14	1		*SIDE BOARD	N/S Cut	300.00 FL	*145.00 FL
15	1		*SIDE STAND	Damaged	95.00 FL	*95.00 FL
16	1		*MAINT STAND	Not Necessary	135.00 FL	*- FL
17	2		*FRONT FOOTREST	Not Necessary	96.00 FL	*- FL
18	2		*FRONT FOOTREST BRACKETS	Not Necessary	220.00 FL	*- FL
19	1		*GEAR PEDAL	Bent	58.00 FL	*58.00 FL
20	2		*REAR FOOTREST	Serviceable	104.00 FL	*- FL
21	1		*ENGINE COVER	Cracked	480.00 FL	*280.00 FL
22	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
23	2		*FORK OILS	Necessary (1 SIDE)	30.00 FS	*15.00 FS
24	2		*FORK OIL SEALS	Necessary (1 SIDE)	56.00 FS	*20.00 FS
25	1		*SET STEERING CONE	Necessary	95.00 FS	*60.00 FS
26	1		*ENGINE COVER GASKET	Necessary	65.00 FS	*65.00 FS
27	1		*ENGINE OIL (50%)	Necessary	35.00 FS	*17.50 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,370.00	1,087.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	405.10	91.00
Total Parts (\$\$)	3,964.90	996.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	60.00	60.00
2	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	480.00	250.00
Gross Labour Cost (\$\$)			1,000.00	310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >