

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 4506S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT GRILLE	MTG CRACKED	485.30	485.30
1	FRONT GRILLE CLIPS (1 SET)	NECESSARY	22.00	22.00
1	FRONT BUMPER	CRACKED	710.60	646.00
1	FRONT BUMPER CLIPS (1 SET)	NECESSARY	35.00	35.00
1	LH FRONT BUMPER RETAINER	SERVICEABLE	35.00	-
1	FRONT BUMPER SPONGE	SERVICEABLE	265.30	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	540.60	-
1	LH FRONT BUMPER FOG LAMP CHROME RIM	DENTED	85.20	85.20
1	LH HEAD LAMP INNER PANEL	CRACKED	682.80	682.80
1	RH HEAD LAMP	MTG CRACKED	1,477.60	1,343.30
1	LH HEAD LAMP	CRACKED	1,477.60	1,343.30
1	FRONT GRILLE EMBLEM	NECESSARY	95.80	95.80
1	LH FRONT BUMPER FOG LAMP	SERVICEABLE	379.00	-
	LESS 10% DISCOUNT		-629.18	-473.87
			5,662.62	4,264.83
	LABOUR			
	TO REMOVE FRONT DAMAGED PARTS, TO JACK OUT FRONT SUPPORT PANEL, FRONT BODY, AND TO STRAIGHTEN OUT FRONT CHASSIS, TO RESHAPE AND REPAIR LH FRONT FENDER AND INNER PANEL, HEAD LAMP INNER PANEL, FRONT SUPPORT PANEL, AND ADJUST BODY PANEL ALIGNMENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		550.00	400.00
	TO SPRAY PAINT AFFECTED FRONT AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND METERIAL.		580.00	400.00
	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY.TO FOCUS HEADLAMP.		25.00	20.00
			1,155.00	820.00
	GRAND TOTAL		6,817.62	5,084.83

Report Ref No. CS/SMO21007813/Kqf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,000.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMO21007813/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser