EPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 19 Jul 2021)

M1-SUV SUZUKI VITARA 1.6 GLX (A) (Catalogue:Merimen Singapore 1.0)

abour. Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH5954E)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES

marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

	Qty Part No.	Particulars		%Disc	%Depr	Amount
		*REAR FENDER GARNISH RH SUL		0.00	0.00	*275.00 F
2	1	*REAR FENDER RH (REPAIR)		0.00	0.00	
3	1	*REAR BUMPER (REPAIR)		0.00	0.00	2 11 1150
4	1	PEAD BUMBED DETAINED DU VC TL		0.00	0.00	*38.00 F
5	10	*REAR BUMPER CLIPS * 8 A A		0.00	0.00	*38.50 F
F=Fra	nchise part.		Sub Total (S\$) + Margin on L,N Items 15.00% (S\$)		275	351.50 52.73
			Total Parts (S\$)	NO.	316.25	404.23

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

TO KNOCK AND STRAIGHTEN REAR FENDER RH, REPAIR REAR BUMPER, REMOVE & REPLACE ACCIDENT 600

SPRAY PAINT REAR FENDER RH, REAR BUMPER

Gross Labour Cost (S\$)

700.00

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

316.25 11:00 600,000 927.25 Roy after repair