

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007822/DVCN2**Date:** 23/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00077592100

Claimant Vehicle No : SMF6929X **Insured Vehicle No :** SLF2520D

Date of Loss: 20/07/2021 Nature of Claim: TP Claim No: SNM21D204003/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF6929X**

Make & Model: SEAT LEON, 1.2 TSI (A) Engine No: CZE852303

Reg. Date: 28/02/2020 (Man. Year: 2019) Chassis No: VSSZZZ5FZKR098245

Colour: White Odometer: 15366 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,546.06	7,992.66	20,553.40	72.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,870.00	1,720.00	5,150.00	74.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,416.06	9,712.66	25,703.40	72.58
Approved Total (Overridden) (\$\$)		7,500.00		
(\$\$)	35,416.06	7,500.00	27,916.06	78.82
+ GST 7.00/7.00% (\$\$)	2,479.12	525.00	1,954.12	78.82
Nett Amount (\$\$)	37,895.18	8,025.00	29,870.18	78.82

INSPECTION

Date of Assignment: 21/07/2021

Date Inspected: 22/07/2021 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2021)
Parts:	144	SEAT LEON 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF6929X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	3,142.00 FL	*2,218.30 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	374.00 FL	*374.00 FL
3	1		*TAILGATE LOGO	Not Necessary	134.00 FL	*- FL
4	1		*TAILGATE LEON EMBLEM	Necessary	150.00 FL	*90.00 FL
5	1		*TAILGATE FR EMBLEM	Necessary	101.00 FL	*101.00 FL
6	2		*TAILGATE LAMP LH/RH	Mounting Cracked	2,184.00 FL	*1,378.60 FL
7	1		*TAILGATE LOCK	Damaged	375.00 FL	*375.00 FL
8	1		*TAILGATE SWITCH	Damaged	321.00 FL	*321.00 FL
9	1		*TAILGATE INNER TRIM BOARD	Mounting Cracked	980.00 FL	*611.30 FL
10	1		*TAILGATE WEATHER STRIP	Serviceable	381.00 FL	*- FL
11	2		*TAILGATE HINGE LH/RH	Not Necessary	258.00 FL	*- FL
12	2		*TAILGATE DAMPER LH/RH	Not Necessary	1,496.00 FL	*- FL
13	2		*TAIL LAMP LH/RH	Not Necessary	3,620.00 FL	*- FL
14	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	368.00 FL	*- FL
15	1		*REAR BUMPER	Distorted/Mounting Cracked	2,290.00 FL	*1,620.00 FL
16	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	350.00 FL	*- FL
17	1		*REAR BUMPER CENTER GARNISH	Cut/Scratched	983.00 FL	*633.00 FL
18	2		*REAR BUMPER NO PLATE LAMP LH/RH	Not Necessary	184.00 FL	*- FL
19	2		*REAR BUMPER SENSOR	Damaged	642.00 FL	*370.00 FL
20	2		*REAR BUMPER SENSOR	Not Necessary	642.00 FL	*- FL
21	4		*REAR BUMPER SENSOR HOLDER	Serviceable	80.40 FL	*- FL
22	1		*REAR BUMPER SENSOR WIREHARNES	Not Necessary	3,294.00 FL	*- FL
23	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	258.00 FL	*- FL
24	1		*REAR BUMPER LOWER LID	Not Necessary	784.00 FL	*- FL
25	1		*REAR BUMPER CARRIER	Not Necessary	492.00 FL	*- FL
26	1		*REAR BUMPER SPONGE	Not fitted	395.00 FL	*- FL
27	1		*REAR REINFORCEMENT BAR	Bent/Dented	1,672.00 FL	*655.20 FL
28	1		*REAR END PANEL	Repair	2,495.00 FL	*- FL
29	1		*REAR END PANEL TOP GARNISH	Not Necessary	385.00 FL	*- FL
30	1		*REAR EXHAUST PIPE	Not Necessary	1,894.00 FL	*- FL
31	1		*REAR EXHAUST MOUNTING	Not Necessary	194.00 FL	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	255.00 FL	*- FL
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
35	1		*TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS
36	1		*TAILGATE LAMP CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
38	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*REAR NO PLATE & GARNISH	Bent	100.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	31,663.40	8,867.40
- List Item Discount on L Items 10.00/10.00% (\$)	3,117.34	874.74
Total Parts (\$)	28,546.06	7,992.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	120.00
6	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	150.00	60.00
7	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
8	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (\$\$)			6,870.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >