



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7794J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,128.60	1,128.60
1	REAR BUMPER REINFORCEMENT	DENTED	564.20	564.20
2	REAR BUMPER SIDE RETAINERS	NOT NECESSARY	96.00	-
1	REAR TOWING COVER	MISSING	28.50	28.50
	LESS 20% DISCOUNT		-363.46	-344.26
			1,453.84	1,377.04
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
			290.00	230.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING/WELDING WORKS.		600.00	200.00
	TO SPRAY PAINTING.		600.00	200.00
	TO SPRAY UNDERSEAL.	NOT NECESSARY	80.00	-
	TO REPLACE REVERSE SENSORS.		80.00	50.00
	TO CHECK WIRING.	NOT NECESSARY	20.00	-
			1,380.00	450.00
	GRAND TOTAL		3,123.84	2,057.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00

Report Ref No. CS/AGI21007823/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.