

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007828/AGS3Q2**Date:** 18/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLN7013B**Insured Vehicle No :** SKS7490S

Date of Loss: 19/07/2021

Nature of Claim:

TP

Claim No: 1508268675SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLN7013B**

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No: CVN034907

Reg. Date: 15/05/2017 (Man. Year: 2017)

Chassis No: WAUZZZF40HA135400

Colour: Grey

Odometer: 55625 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,381.00	1,688.80	10,692.20	86.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	1,792.00	3,210.00	64.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,383.00	3,480.80	13,902.20	79.98
+ GST 7.00/7.00% (S\$)	1,216.81	243.66	973.15	79.98
Nett Amount (S\$)	18,599.81	3,724.46	14,875.35	79.98
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,126.46		

INSPECTION

Date of Assignment: 27/07/2021

Date Inspected: 27/07/2021

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,111.00 FS	*1,688.80 FS
2	1	*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2	*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	210.00 FS	*- FS
5	1	*RADIATOR AIR GUIDE RH	Not Necessary	63.00 FS	*- FS
6	1	*FRONT AIR GUIDE GRILLE RH	Not Necessary	135.00 FS	*- FS
7	1	*FRONT BUMPER GUIDE SECTION RH	Not Necessary	38.00 FS	*- FS
8	1	*FRONT FENDER RH	Repair	767.00 FS	*- FS
9	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
10	1	*FRONT FENDER CLOSING ELEMENT RH	Not Necessary	72.00 FS	*- FS
11	1	*FRONT FENDER BRACKET RH	Not Necessary	35.00 FS	*- FS
12	1	*FRONT FENDER BRACE RH	Not Necessary	118.00 FS	*- FS
13	1	*FRONT FENDER DEFORMATION ELEMENT RH	Not Necessary	49.00 FS	*- FS
14	6	*FRONT FENDER POP RIVET	Not Necessary	20.00 FS	*- FS
15	1	*FRONT WHEEL HOUSING LINER RH	Not Necessary	241.00 FS	*- FS
16	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS RH (NPA)	Not Necessary	0.00 FS	*- FS
17	1	*FRONT WHEEL SPOILER RH	Not Necessary	73.00 FS	*- FS
18	1	*FRONT FENDER LEDGE COVER RH	Not Necessary	23.00 FS	*- FS
19	1	*LED HEADLIGHT RH	Not Necessary	7,693.00 FS	*- FS
20	1	*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	Not Necessary	210.00 FS	*- FS
21	1	*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **12,381.00** **1,688.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER RHS FRONT FENDER AND RHS HEADLIGHT RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,002.00	1,792.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >