



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 3807G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (BUCKLED)	NOT CONSISTENT WITH THE IMPACT	1,482.96	-
1	REAR BUMPER LOWER	SERVICEABLE	689.72	-
1	REAR BUMPER CENTER SUPPORT BRACKET	SERVICEABLE	477.84	-
1	BLIND SPOT SENSOR	SERVICEABLE	457.92	-
1	REAR REFLECTOR LH	SERVICEABLE	449.80	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	288.96	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	799.24	-
1	REAR FENDER BRACKET LH	TO REPAIR SEE LABOUR	152.60	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,295.50	-
1	REAR BUMPER BRACKET	SERVICEABLE	268.70	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	614.80	-
1	FRONT FENDER BRACKET LH	SERVICEABLE	112.60	-
1	FRONT WHEEL ARCH LH	SERVICEABLE	248.60	-
3	FRONT WHEEL ARCH CLIPS @\$4.20	NOT NECESSARY	12.60	-
1	FRONT BUMPER SENSOR LH	SERVICEABLE	273.50	-
1	HEADLAMP BRACKET LH	SERVICEABLE	127.50	-
			7,752.84	-
<u>SPECIAL NETT ITEMS</u>				
6	REAR BUMPER CLIPS @\$7.00 (SN)	NOT NECESSARY	42.00	-
6	FRONT BUMPER CLIPS @\$7.00 (SN)	NOT NECESSARY	42.00	-
			84.00	-
<u>LABOUR</u>				
TO PANEL BEATING,DAMAGED AND REALIGN THE FRONT BUMPER,FRONT FENDER LH,REAR BUMPER,REAR FENDER LH AND ALL NECESSARY ETC.INCLUSIVE OF THE REPAIR OF REAR FENDER LH,REAR FENDER BRACKET LH,FRONT BUMPER AND FRONT FENDER LH.			1,600.00	200.00

Report Ref No. CS/AGI21007832/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEMS FOR PROPER FUNCTION.	NOT NECESSARY	200.00	-
	TO DISMANTLE & REFIX FRONT AND REAR SENSOR.	NOT NECESSARY	250.00	-
	TO DO WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	TO APPLY RUST PROOFING.	NOT NECESSARY	150.00	-
	TO PUTTY & SPRAY PAINTING ON REAR BUMPER, REAR FENDER LH, FRONT BUMPER, FRONT FENDER LH AND ALL NECESSARY ETC.		1,400.00	400.00
			3,780.00	600.00
GRAND TOTAL			11,616.84	600.00
RECOMMENDED COST OF REPAIRS				600.00

Report Ref No. CS/AGI21007832/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.