7/30/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/III15013900/KPA3Q2-1

Date:

30/07/2021

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MPRE0003 SHC6194Z

Engine No:

Chassis No:

Odometer:

Claimant Vehicle No : SH

SHD943M 13/08/2015 Insured Vehicle No: Nature of Claim:

TP

Claim No:

MCP141598

JTDER12W203002821

1ZZ3237878

703766 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD943M

Make & Model: TOYOTA WISH, 1.8 (A)

Reg. Date: 31/08/2009 (Man. Year: 2009)

Colour: Red Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

res

CONDITION OF TYRES

Front Left Side:

Front Tyre Size: 195/65 R15

195/65 R15 Rear Tyre Size: Falken 8 mm Rear Left Side:

195/65 R15 Falken 5 mm

Front Right Side: Falken 8 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,016.17	1,227.50	1,788.67	59.30
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,810.00	840.00	2,970.00	77.95
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,826.17	2,067.50	4,758.67	69.71
	Approved Total (Overridden) (S\$)		1,650.00		

(\$\$)	6,826.17	1,650.00	5,176.17	75.83
+ GST 7.00/7.00% (S\$)	477.83	115.50	362.33	75.83
Nett Amount (S\$)	7,304.00	1,765.50	5,538.50	75.83
+ Car Rental (2.0 x S\$93.09/day) (S\$)		186.18		
	(S\$)	1,951.68		
Liable Amou	ınt (85.00%) (S\$)	1,658.93		
+ Legal Costs/Dis	bursements (S\$)	350.00		
N	lett Liability (S\$)	2,008.93		
Global Sum	Settlement (S\$)	2,000.00		

INSPECTION

Date of Assignment: 14/08/2015

Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1 Date Inspected: Inspected At: 14/08/2015 Singapore 729346

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG CHEW HSIAO TONG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Mar 2017)

TOYOTA WISH 1.8 (A) (Model not available in database) Parts: N/A

Repairer's (Price-denominated Standard List) Labour:

(Unsubmitted, no print-code for SHD943M) **Print Code:**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	487.80 FL	*- FL
2	1	*FRONT BUMPER LOWER ABSORBER	Serviceable	105.00 FL	*- FL
3	1	*FRONT BUMPER REINFORCEMENT	Repair	270.00 FL	*- FL
4	1	*FRONT BUMPER SIDE RETAINER RH	Serviceable	57.30 FL	*- FL
5	1	*FRONT HEADLAMP RH	Mtg Cracked	672.00 FL	*672.00 FL
6	1	*FRONT FENDER RH	Bent	698.00 FL	*698.00 FL
7	1	*FRONT FENDER LINER RH	Serviceable	307.62 FL	*- FL
8	1	*RADIATOR GRILLE	Serviceable	169.80 FL	*- FL
9	1	*WINDSCREEN WASHER TANK	Serviceable	138.33 FL	*- FL
10	1	*WINDSCREEN WASHER TANK MOTOR	Serviceable	222.38 FL	*- FL
11	1	*SET BUMPER FASTENER CLIP FRT	Necessary	35.00 FS	*35.00 FS
12	1	*SET FRONT FENDER LINER FASTENER CLIP	Not Necessary	20.00 FS	*- FS
13	1	*CNG STICKER	Necessary	30.00 FS	*15.00 FS
14	1	*FRONT FENDER ADVERTISEMEN STICKER RH	Necessary	250.00 FS	*150.00 FS
15	1	*FRONT TYRE RH	Serviceable	180.00 FS	*- FS
16	1	*FRONT TYRE RIM RH	Serviceable	120.00 FS	*- FS
17	1	*HUB CAP RH	Serviceable	35.00 FS	*- FS
F=Fr	ranchise part. S=SpcNett	:. L=ListItemDisc.			
			Sub Total (S\$)	3,798.23	1,570.00
			- List Item Discount on L Items 25.00/25.00% (S\$)	782.06	342.50
			Total Parts (S\$)	3,016.17	1,227.50

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	300.00
TO RUST-PROOFING OF THE AFFECTED AREAS	New	220.00	30.00
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,350.00	400.00
TO CHECK ELECTRICAL LIGHTING CONCERNED	New	120.00	20.00
TO REMOVE AND REPLACE CORPORATE STICKER	New	330.00	30.00
TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross L	abour Cost (S\$)	3,810.00	840.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME TO RUST-PROOFING OF THE AFFECTED AREAS PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION TO CHECK ELECTRICAL LIGHTING CONCERNED TO REMOVE AND REPLACE CORPORATE STICKER TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME TO RUST-PROOFING OF THE AFFECTED AREAS New PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION New TO CHECK ELECTRICAL LIGHTING CONCERNED New TO REMOVE AND REPLACE CORPORATE STICKER New TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT New	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME TO RUST-PROOFING OF THE AFFECTED AREAS PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION TO CHECK ELECTRICAL LIGHTING CONCERNED TO REMOVE AND REPLACE CORPORATE STICKER TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. New 170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >