

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21007836/R1VF3N2**Date:** 20/09/2021**REFERENCE**

Insured/Claimant:	TAN TAI KOON	Policy No:	1900157820	
Date of Loss:	22/07/2021	Nature of Claim:	OD	Claim No: 4974264246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP1019C		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UHX6862
Reg. Date:	11/09/2019 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH002564
Colour:	Grey	Odometer:	38540 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,847.63	5,707.26	2,140.37	27.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,770.00	8,150.00	1,620.00	16.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,617.63	13,857.26	3,760.37	21.34
+ GST 7.00/7.00% (S\$)	1,233.23	970.01	263.22	21.34
Nett Amount (S\$)	18,850.86	14,827.27	4,023.59	21.34

INSPECTION

Date of Assignment: 22/07/2021

Date Inspected: 22/07/2021 Inspected At:

Estimated Period of Repair: 14.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*LAMP ASSY,LICENSE PLATE	Serviceable	102.00 FL	*- FL
2	1		*LAMP ASSY,COMB,RR LH	Cracked	337.00 FL	*337.00 FL
3	1		*LAMP ASSY,COMB,RR RH	Serviceable	337.00 FL	*- FL
4	1		*REFLECTOR	Serviceable	23.00 FL	*- FL
5	1		*REFLECTOR	Serviceable	23.00 FL	*- FL
6	1		*FACE,RR BUMPER	Deformed	751.00 FL	*751.00 FL
7	1		*BRACKET,RR BUMPER,LH	Necessary	28.00 FL	*28.00 FL
8	1		*BRACKET,RR BUMPER,RH	Necessary	28.00 FL	*28.00 FL
9	1		*PANEL,QTR,OTR LH	Buckled	759.00 FL	*759.00 FL
10	1		*PANEL,RR COMB LAMP HSG,LH	Bent	60.00 FL	*60.00 FL
11	1		*FLOOR,RR	Serviceable	956.00 FL	*- FL
12	1		*PANEL,RR END	Bent	427.00 FL	*427.00 FL
13	1		*GLASS,RR WINDOW	Serviceable	544.00 FL	*- FL
14	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
15	3		*SPECER,RR WINDOW	Necessary	27.00 FL	*27.00 FL
16	1		*PANEL,TRUNK LID	Bent	795.00 FL	*795.00 FL
17	1		*HINGE,TRUNK LID,LH	Serviceable	203.00 FL	*- FL
18	1		*HINGE,TRUNK LID,RH	Serviceable	203.00 FL	*- FL
19	1		*WEATHERSTRIP,TRUNK LID	Necessary	157.00 FL	*157.00 FL
20	1		*STRIKER,TRUNK LID LATCH	Serviceable	20.00 FL	*- FL
21	1		*LATCH,TRUNK LID	Bent	218.00 FL	*218.00 FL
22	1		*GARNISH,RR END PANEL	Cracked	336.00 FL	*336.00 FL
23	1		*MARK,THREE-DIA	Necessary	70.00 FL	*70.00 FL
24	1		*MARK,ATTRAGE	Necessary	21.00 FL	*21.00 FL
25	1		*TRIM,RR END	Deformed	66.00 FL	*66.00 FL
26	1		*BOARD,TRUNK ROOM FLOOR	Cracked	195.00 FL	*195.00 FL
27	1		*CARPET,TRUNK ROOM	Serviceable	170.00 FL	*- FL
28	1		*UNPAINTED BODYKITS	Cracked	1,643.00 F	*1,643.00 F
29	1		*SHARK FUN ANTENNA,ATTRAGE GREY	Not Necessary	123.00 F	-
30	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
31	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
32	1		*REAR LH TYRE	Necessary	260.00 FS	*260.00 FS
33	1		*SET REVERSE SENSOR	Necessary	220.00 FS	*220.00 FS
34	1		*MIVIC EMBLEM	Necessary	30.00 FS	*30.00 FS
35	1		*BUZZER,KEYLESS OPERATION, RR (Supplementary)	Broken	91.00 FL	*91.00 FL
36	1		*ANT,KEYLESS OPERATION,RR (Supplementary)	Broken	96.00 FL	*96.00 FL
37	4		*CLIPS (Supplementary)	Necessary	12.00 FL	*12.00 FL
38	4		*GROMMET (Supplementary)	Necessary	12.00 FL	*12.00 FL
39	2		*GROMMET (Supplementary)	Necessary	6.00 FL	*6.00 FL
40	1		*SHIELD,RR WHEELOUSE,LH (Supplementary)	Torn	40.00 FL	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,485.00	6,751.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,637.37	1,043.74
Total Parts (\$\$)	7,847.63	5,707.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER,BOOT,END PANEL,FLOOR PANEL,REAR LH FENDER,REAR TYRE PANEL,BODYKIT & AFFECTED AREA.REPAIR ON REAR RH FENDER	New	4,050.00	3,375.00
2	PAINT WORK ON REAR BUMPER,BOOT,END PANEL,FLOOR PANEL,REAR LH TAILLAMP PANEL,BODYKIT & BOTH REAR FENDER	New	2,800.00	2,200.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00
4	REMOVE & REPLACE REAR BODY KIT	New	80.00	80.00
5	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
6	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
7	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	225.00	120.00
8	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	120.00	120.00
9	REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR	New	450.00	450.00
10	TO TRANSFER BOOT ATTACHMENTS TO NEW PANEL	New	120.00	120.00
11	TO APPLY SEALANT ON AFFECTED AREA	New	120.00	80.00
12	PERFORM RUST PREVENTION	New	120.00	80.00
13	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
14	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
15	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
16	TO TRANSFER REAR LH RIM INCLUDING BALANCING	New	30.00	30.00
17	TO SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	50.00
18	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	320.00	320.00
19	REPAIR REAR FLOOR PANEL (Supplementary)	New	225.00	225.00
20	RESPRAY REAR FLOOR PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			9,770.00	8,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >