

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG21007849/ETF3E2

Date: 03/09/2021

REFERENCE

Insured/Claimant: OH ZHEN CHANG Policy No: 29146919ATM
Date of Loss: 21/07/2021 Nature of Claim: OD Claim No: 637155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS8634B**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 ECO (A) Engine No: 1ZR0A02451
Reg. Date: 10/10/2017 (Man. Year: 2017) Chassis No: MR053REH604572804
Colour: White Odometer: 71935 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$72,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,971.69	14,419.07	1,552.62	9.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,577.00	6,543.00	2,034.00	23.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,548.69	20,962.07	3,586.62	14.61
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	24,048.69	20,462.07	3,586.62	14.91
+ GST 7.00/7.00% (S\$)	1,683.41	1,432.34	251.07	14.91
Nett Amount (S\$)	25,732.10	21,894.41	3,837.69	14.91

INSPECTION

Date of Assignment: 22/07/2021
Date Inspected: 23/07/2021 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462
Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2021)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 ECO (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS8634B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*SEALANT	Necessary	60.00 FS	*60.00 FS
3	1		*COVER, FR BUMPER, L/	Broken	402.15 FS	*402.15 FS
4	1		*ABSORBER, FR BUMPER	Broken	84.82 FS	*84.82 FS
5	1		*REINFORCEMENT, FR	Not Necessary	302.77 FS	*- FS
6	1		*SUPPORT, FR BUMPER S	Broken	51.52 FS	*51.52 FS
7	1		*SUPPORT, FR BUMPER S	Broken	51.52 FS	*51.52 FS
8	1		*GRILLE ASSY, RADIATO	Broken	538.05 FS	*538.05 FS
9	1		*COVER, RADIATOR RH	Missing	60.97 FS	*60.97 FS
10	6		*PIECE, RR BUMPER	Necessary	18.42 FS	*18.42 FS
11	1		*HOOD SUB-ASSY	Dented	944.55 FS	*944.55 FS
12	1		*FENDER SUB-ASSY, RH	Dented	689.55 FS	*689.55 FS
13	1		*FENDER SUB-ASSY, LH	Dented	689.55 FS	*689.55 FS
14	1		*HINGE ASSY, HOOD RH	Bent	44.55 FS	*44.55 FS
15	1		*HINGE ASSY, HOOD, LH	Bent	44.55 FS	*44.55 FS
16	1		*LOCK ASSY, HOOD	Bent	102.15 FS	*102.15 FS
17	1		*HOLDER, HOOD STAY	Missing	15.37 FS	*15.37 FS
18	1		*SUPPORT SUB-ASSY	Dented	862.12 FS	*862.12 FS
19	1		*SUPPORT SUB-ASSY, HO	Bent	125.02 FS	*125.02 FS
20	1		*PLATE, LUGGAGE COMPT	Necessary	26.92 FS	*26.92 FS
21	1		*PLATE, LUGGAGE COMPT	Necessary	26.92 FS	*26.92 FS
22	1		*HEADLAMP ASSY, RH	Broken	1,883.92 FS	*1,883.92 FS
23	1		*HEADLAMP ASSY, LH	Broken	1,883.92 FS	*1,883.92 FS
24	1		*A/C CONDENSER ASSY	Dented	1,365.15 FS	*1,365.15 FS
25	2		*COOLANT, SLLC&&&	Necessary	120.44 FS	*120.44 FS
26	1		*RADIATOR ASSY	Dented	1,627.20 FS	*1,627.20 FS
27	1		*SHROUD FAN	Broken	224.92 FS	*224.92 FS
28	1		*RADIATOR SHROUD NO 2,	Broken	76.20 FS	*76.20 FS
29	1		*FAN, BLADE	Broken	136.87 FS	*136.87 FS
30	1		*MOTOR, COOLING FAN	Not Necessary	405.75 FS	*- FS
31	1		*RADIATOR RESERVE TANK	Crushed	144.15 FS	*144.15 FS
32	1		*TUBE & ACCESSORY ASS	Bent	570.07 FS	*570.07 FS
33	1		*INLET, AIR CLEANER	Not Necessary	145.20 FS	*- FS
34	1		*MANIFOLD ASSY	Not Necessary	678.90 FS	*- FS
35	1		*CLAMP SUB-ASSY, BATT	Bent	27.60 FS	*27.60 FS
36	1		*DEFLECTOR, RADIATOR	Broken	60.97 FS	*60.97 FS
37	1		*DEFLECTOR, RADIATOR	Broken	61.42 FS	*61.42 FS
38	1		*INSULATOR, HOOD	Crushed	212.32 FS	*212.32 FS
39	1		*COVER, CYLINDER	Broken	289.72 FS	*289.72 FS
40	1		*AIR-CLEANER ASSY	Broken	865.50 FS	*865.50 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **15,971.69** **14,419.07**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE AND REFOCUS HEADLAMP	New	162.00	162.00
2	RESET AND REPROGRAMME ECU	New	162.00	162.00
3	REMOVE AIR CON COMPONENTS TO REGAS AND REPLACE NEW PARTS	New	324.00	324.00
4	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	3,717.00	2,655.00
5	REPLACE ENGINE COMPONENTS TO ASSIST REPAIR	New	324.00	0.00
6	REMOVE ALL NECESSARY DAMAGED PARTS. TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, BONNET, FRT SUPPORT PANEL, BOTH FRT FENDER AND AFFECTED PORTION OF CAR	New	3,888.00	3,240.00
			Gross Labour Cost (\$\$)	8,577.00
				6,543.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >