

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007850/KGS3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SJZ8544P

Date of Loss: 11/07/2021

Policy No:

Insured Vehicle No :

SBQ2383T

Nature of Claim:

TP

Claim No:

5263679272SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJZ8544P**

Make & Model: SUZUKI SWIFT, 1.5 GL (A)

Reg. Date: 30/12/2010 (Man. Year: 2010)

Colour: Metallic Grey

Engine Capacity: 1490 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: M15A1412118

Chassis No: JSAEZC21S00566544

Odometer: 181568 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Yes

Steering (Serviceable):

Engine Modification:

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Front Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

185/65 R15

Dunlop 7 mm

Dunlop 7 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,297.35	1,089.10	1,208.25	52.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	720.00	1,840.00	71.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,857.35	1,809.10	3,048.25	62.76
Approved Total (Overridden) (S\$)		1,450.00		

(S\$)	4,857.35	1,450.00	3,407.35	70.15
+ GST 7.00/7.00% (S\$)	340.01	101.50	238.51	70.15
Nett Amount (S\$)	5,197.36	1,551.50	3,645.86	70.15
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/07/2021

Date Inspected: 14/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Ding Auto Pte Ltd (HQ)
 176 Sin Ming Drive #04-06, Sin Ming Autocare
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Buckled / Cracked	690.95 FL	*575.00 FL
2	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	76.95 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Serviceable	80.65 FL	*- FL
4	1		*FRONT BUMPER RETAINER RHS	Distorted	31.15 FL	*31.15 FL
5	1		*FRONT BUMPER RETAINER LHS	Serviceable	31.15 FL	*- FL
6	1		*FRONT BUMPER LOWER GARNISH RHS	Dented / Cut	16.55 FL	*16.55 FL
7	1		*FRONT BUMPER LOWER GARNISH LHS	Serviceable	16.55 FL	*- FL
8	1		*BUMPER TOWING CAP	Dented	29.60 FL	*29.60 FL
9	1		*FRONT REINFORCEMENT	Bent	190.05 FL	*190.05 FL
10	1		*FRONT TOP SUPPORT PANEL	Repair	79.50 FL	*- FL
11	1		*FRONT LOWER SUPPORT PANEL	Repair	95.90 FL	*- FL
12	1		*FRONT LOWER TRIM PANEL	Repair	163.85 FL	*- FL
13	1		*ENGINE LOWER COVER RH	Serviceable	59.70 FL	*- FL
14	1		*ENGINE LOWER COVER LH	Serviceable	59.70 FL	*- FL
15	1		*HEADLAMP ASSY RH	Mtg Cracked	437.10 FL	*386.00 FL
16	1		*HEADLAMP ASSY LH	Serviceable	437.10 FL	*- FL
17	1		*CENTRE GRILLE BADGE	Serviceable	29.85 FL	*- FL
18	1		*FRONT BUMPER & FENDER INNER SHIELD BRACKETS /CLIPS	Not Necessary	100.00 FS	*- FS
19	1		*CAR NUMBER PLATE & FRAME	Cracked	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,676.30	1,273.35
- List Item Discount on L Items 15.00/15.00% (\$\$)	378.95	184.25
Total Parts (\$\$)	2,297.35	1,089.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	New	800.00	300.00
2	SPRAY PAINT ,FRT BUMPER FENDER RH ,FENDER LH & BONNET (INNER/OUTER)	New	1,500.00	400.00
3	REMOVE & REFIT BUMPER COMPONENTS	New	80.00	0.00
4	REMOVE & REFIT HEADLAMP RH/LH }	New	120.00	20.00
5	ALIGN HEADLAMP AND TEST WIRING }	New	60.00	0.00
Gross Labour Cost (S\$)			2,560.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >