

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III21007046/R1QF3E2-1**Date:** 05/08/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJJ1376M **Insured Vehicle No :** SLV9651D
 Date of Loss: 22/06/2021 Nature of Claim: TP Claim No: MFL2021D0003001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ1376M**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4786262
 Reg. Date: 02/09/2008 (Man. Year: 2008) Chassis No: MR053ZEE106115131
 Colour: Grey Odometer: 351090 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 5 mm Rear Left Side: Nexen 5 mm
 Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,512.27	1,869.62	4,642.65	71.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	870.00	2,780.00	76.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,162.27	2,739.62	7,422.65	73.04
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	10,162.27	2,200.00	7,962.27	78.35

INSPECTION

Date of Assignment: 22/07/2021
 Date Inspected: 28/06/2021 Inspected At: A-Tec Motorz Pte Ltd (HQ)
 39 Woodlands Close #02-43, Mega@Woodlands
 Singapore 737856
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ1376M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Torn	1,236.50 FL	*562.00 FL
2	1		*FRONT BUMPER SIDE RETAINERS (2PCS)	Necessary (1Pc Only)	157.00 FL	*78.50 FL
3	1		*FRONT LOGO	Necessary	68.50 FL	*68.50 FL
4	1		*FRONT RIGHT HEAD LAMP	Broken	958.00 FL	*786.00 FL
5	1		*FRONT RIGHT FOG LAMP	Broken	263.00 FL	*263.00 FL
6	1		*FRONT RIGHT FOG LAMP CHROME GARNISH	Chipped	38.50 FL	*38.50 FL
7	1		*FRONT RIGHT FOG LAMP HOUSING	Not Necessary	125.00 FL	*- FL
8	1		*FRONT RIGHT FENDER	Crushed	945.00 FL	*603.00 FL
9	1		*FRONT RIGHT WHEELHOUSE INNER COVER	Reuse	215.00 FL	*- FL
10	1		*FRONT RIGHT SUSPENSION ASSY	Not Necessary	893.50 FL	*- FL
11	1		*FRONT RIGHT KNUCKLE	Not Necessary	432.30 FL	*- FL
12	1		*FRONT RIGHT WHEEL BEARING	Not Necessary	279.40 FL	*- FL
13	1		*FRONT RIGHT CONTROL ARM W BUSHING	Not Necessary	368.00 FL	*- FL
14	1		*FRONT RIGHT STABILIZER LINK	Not Necessary	135.00 FL	*- FL
15	1		*FRONT RIGHT DRIVESHAFT	Not Necessary	435.00 FL	*- FL
16	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
17	2		*FRONT WHEELHOUSE INNER COVER CLIPS	Necessary	100.00 FS	*40.00 FS
18	3		*FRONT RIGHT RIM	Not Necessary	1,000.00 FS	*- FS
19	4		*FRONT RIGHT TYRE	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,149.70	2,469.50
- List Item Discount on L Items 25.00/25.00% (S\$)	1,637.43	599.88
Total Parts (S\$)	6,512.27	1,869.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT AND REPLACE FRONT UNDERCARRIAGE	New	350.00	0.00
2	TO REMOVE, REFIT, AND REPLACE FRONT LEFT FENDER	New	230.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT CALIBRATION	New	160.00	0.00
4	TO CONDUCT WHEEL BALANCING CALIBRATION	New	50.00	0.00
5	TO CALIBRATE AND CHECK FRONT HEADLAMPS FOR BEAM FOCUSING	New	80.00	30.00
6	TO REMOVE, REFIT AND REPLACE DAMAGED LAMPS AND TO CHECK FRONT ELECTRICAL WIRING	New	80.00	0.00
7	TO APPLY ANTI-RUST UNDERCOATING ON REPAIRED AND REPLACED PANELS	New	500.00	40.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE DAMAGED PARTS, INCLUDING CUT AND WELD, RE-ALIGNMENT OF BODY STRUCTURE AND DAMAGE CONSISTENT WITH THE ACCIDENT	New	1,000.00	400.00
9	TO RESPRAY PAINT INCLUDING POLISHING AND WAXING ON THE REPAIRED BODY PARTS, PORTIONS CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00
Gross Labour Cost (\$)			3,650.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >