

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2202124

3 ANSON ROAD #16-00 INV Date 13/04/2022

SPRINGLEAF TOWER Reference CC6/CTI21007857/Kea3q2 SINGAPORE 079909

Code CTI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SLT 8596Y

Insured Veh. SJL 3692B

Claim No. SNM21D204044/C02

Policy No. DMPCSNW00160192000

Accident Date 21/07/2021

Inspection Date 23/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio	nale Des Experts En Au	itomo	bile			
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Re	ef:	CC6/CTI21007857/Kea3q2			
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Da	ate:	13/04/2022			
			Co	ode:	CTI			
1.	Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SJL 3692B	Veh. Inspected		SLT 8596Y			
	Policy No.	DMPCSNW00160192000	Coverage (\$)		0.00			
	Claim No.	SNM21D204044/C02	Excess (\$)		0.00			
	Assign From		Assign Date		23/07/2021			
2.		Vehicle Partic	culars & Condition					
	Make & Model	HYUNDAI ELANTRA (A)	c.c		1591			
	Engine No.	HIDDEN	Year of Reg.		2017			
	Chassis No.	KMHD841CMJU568639	Colour		METALLIC RED			
	Odometer	59035 KM	Steering		IN ORDER			
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM			
	General	GOOD						
3.		Conditi	ons of Tyres					
		Size	Make		Balance			
	R/H Front Tyre	195/65 R15	FIRENZA		9 mm			
	L/H Front Tyre	195/65 R15	FIRENZA		9 mm			
	R/H Rear Tyre	195/65 R15	FIRENZA		9 mm			
	L/H Rear Tyre	195/65 R15	FIRENZA		9 mm			
4.	Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.							
	DAMAGES SEE D	ETAILS.						
5.		Genera	I Information					
	Accident Date	21/07/2021	Inspection Date		23/07/2021			
	Survey held at	CITY AUTO PTE LTD						
		BLK 8, SIN MING IND. ESTATE						
		#01-60/62 Sector C						
		SINGAPORE 575643.						
5a.	1		emarks					
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W						
5b.		Estimate	Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days							
	-							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 8596Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
2	REAR BUMPER REFLECTOR @\$40.80	O/S CUT / N/S CRACKED	81.60	81.60
2	REAR BUMPER RETAINER @\$44.30	N/S DISTORTED	88.60	44.30
2	REAR BUMPER REINFORCEMENT WITH BRACKET @ \$294.80	BENT (1 PCS ONLY)	589.60	339.00
2	REAR BUMPER UPPER BRACKET @\$4.00	SERVICEABLE	8.00	-
1	REAR BUMPER LOWER LID	BENT	280.10	280.10
12	REAR BUMPER CLIPS @\$2.00	NECESSARY	24.00	24.00
1	REAR UNDER FLOOR COVER	CRACKED	57.20	57.20
1	REAR BOOT	BENT	1,782.40	1,782.40
1	REAR BOOT WEATHERSTRIP	SERVICEABLE	92.50	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	116.20	-
1	REAR BOOT LOGO	NECESSARY	28.00	28.00
1	REAR BOOT EMBLEM -ELANTRA	NECESSARY	48.80	48.80
1	REAR BOOT EMBLEM-S	NECESSARY	58.00	58.00
2	REAR BOOT LAMP @\$285.00	N/S CUT / O/S SERVICEABLE	570.00	285.00
2	TAIL LAMP @\$388.00	SERVICEABLE	776.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	454.70	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	59.80	-
	LESS 20% DISCOUNT		-1,114.98	-697.56
			4,459.92	2,790.24
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	DENTED	350.00	200.00
1	NUMBER PLATE (SN)	DENTED	20.00	20.00
1	NUMBER PLATE CASING (SN)	DENTED	25.00	25.00
			395.00	245.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND LIGHTING.		60.00	20.00

Report Ref No. CC6/CTI21007857/Kea3q2



**RECOMMENDED COST OF REPAIRS** 

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

4,495.24

	O INSTALL REVERSE SENSOR . O REMOVE AND REFIT REAR TRIMS AND UPHOLSTERY		50.00	50.00
TO	O REMOVE AND REFIT REAR TRIMS AND UPHOLSTERY			
			120.00	60.00
	O SUPPLY PANEL SEALANT AND TO SEAL OFF WELD SPOT SEAMS AND GAPS.	NOT NECESSARY	80.00	-
TO	O SPRAY UNDER COATING.		80.00	30.00
W	O KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING VELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.		900.00	500.00
SI	PRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,000.00	800.00
			2,290.00	1,460.00
G	RAND TOTAL		7,144.92	4,495.24

Report Ref No. CC6/CTI21007857/Kea3q2

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLT 8596Y

#### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLT 8596Y

#### **RE-INSPECTION**













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### PHOTOGRAPHS FOR VEHICLE NO. SLT 8596Y

#### **RE-INSPECTION**











