



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108861

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 27/12/2021
Reference CC3/CTI21007863/Ers3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 5537E
Insured Veh. GBC 6228G
Claim No. SNM21D204023/LKKDS
Policy No. DMCVSNW0076992001
Accident Date 19/07/2021
Inspection Date 22/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21007863/Ers3q2 Date: 27/12/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 6228G	Veh. Inspected	SHB 5537E	
Policy No.	DMCVSNW0076992001	Coverage (\$)	0.00	
Claim No.	SNM21D204023/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	22/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU503572405	Colour	MAROON	
Odometer	394036 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	MICHELIN	5 mm	
L/H Front Tyre	195/50 R15	MICHELIN	5 mm	
R/H Rear Tyre	195/50 R15	MICHELIN	5 mm	
L/H Rear Tyre	195/50 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/07/2021	Inspection Date	22/07/2021	
Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5537E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	EMBLEM,SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	WIPER WASHER JAR (DISC 25%)	CRUSHED	183.60	137.70
1	COVER ,RADIATOR (DISC 25%)	BROKEN	227.80	170.85
1	COVER ,FR BUMPER (DISC 25%)	BROKEN	495.50	371.63
1	COVER ,FR BUMPER LH (DISC 25%)	MISSING	28.10	21.08
1	COVER ,FR BUMPER RH (DISC 25%)	MISSING	28.10	21.08
10	CLIPS PIECE ,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GRILLE SUB-ASSY (DISC 25%)	BROKEN	335.60	251.70
1	EMBLEM ASSY FRONT (DISC 25%)	MISSING	87.10	65.33
1	GRILLE ,RADIATOR (DISC 25%)	BROKEN	165.00	123.75
1	BRACKET ,FR BUMPER (DISC 25%)	BROKEN	99.80	74.85
1	SUPPORT ,FR BUMPER RH (DISC 25%)	BROKEN	76.90	57.68
1	ABSORBER ,FR BUMPER (DISC 25%)	BROKEN	70.30	52.73
1	LINER ,FR FENDER ,RH (DISC 25%)	TORN	198.40	148.80
1	WIRE ,ENGINE ROOM MAIN (DISC 10%)	BROKEN	6,138.00	5,524.20
1	UNIT ,HEADLAMP ,LH (DISC 10%)	BROKEN	2,558.90	2,303.01
1	UNIT ,HEADLAMP ,RH (DISC 10%)	BROKEN	2,558.90	2,303.01
1	LAMP ASSY ,FOG ,RH (DISC 10%)	BROKEN	910.20	819.18
1	NUMBER PLATE (SN)	BENT	35.00	35.00
1	NUMBER PLATE FRAME (SN)	BROKEN	25.00	25.00
1	PAD ,FR WHEEL LH	NOT NECESSARY	57.70	-
1	LINER ,FR FENDER ,LH	NOT NECESSARY	194.30	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL ,DISC FRONT	NOT NECESSARY	1,555.10	-
1	CAP SUB-ASSY ,WHEEL	NOT NECESSARY	175.80	-
1	PAD ,FR WHEEL RH	NOT NECESSARY	57.70	-
1	LINER ,FR FENDER ,RH	NOT NECESSARY	198.40	-
1	HOSE ,WINDSHIELD WASHER	NOT NECESSARY	14.00	-
1	MOTOR AND PUMP ASSY ,WINDSHIELD WASHER	NOT NECESSARY	245.00	-
1	WIPER WASHER INLET	NOT NECESSARY	55.40	-

Report Ref No. CC3/CTI21007863/Ers3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GUARD ,RADIATOR AIR ,LH	NOT NECESSARY	58.80	-
1	GUARD ,RADIATOR AIR ,RH	NOT NECESSARY	54.60	-
1	SEAL ,RADIATOR TO LH	NOT NECESSARY	24.80	-
1	SEAL ,RADIATOR TO RH	NOT NECESSARY	24.80	-
1	GUIDE ,RADIATOR AIR	NOT NECESSARY	93.90	-
1	COMPUTER SUB-ASSY ,HEADLAMP RH NO.1	NOT NECESSARY	486.40	-
1	COVER ASSY ,ENGINE	NOT NECESSARY	180.10	-
1	HINGE ASSY ,HOOD ,RH	NOT NECESSARY	57.00	-
1	SUPPORT S/A UPPER	NOT NECESSARY	364.90	-
1	SUPPORT SUB-ASSY LOWER	NOT NECESSARY	397.40	-
1	SUPPORT S/A RH	NOT NECESSARY	237.00	-
1	BRACE ,HOOD LOCK SUPPORT	NOT NECESSARY	76.20	-
1	SEAL ,HOOD TO FR END	NOT NECESSARY	24.40	-
1	SUPPORT ,FR BUMPER LH	NOT NECESSARY	82.30	-
1	REINFORCEMENT FRONT UPPER	NOT NECESSARY	691.10	-
1	ABSORBER ,FR BUMPER LOWER	NOT NECESSARY	117.00	-
1	REINFORCEMENT FRONT LOWER	NOT NECESSARY	238.50	-
1	EXTENSION SUBASSY ,LH	NOT NECESSARY	116.30	-
1	EXTENSION SUBASSY ,RH	NOT NECESSARY	116.30	-
1	LAMP ASSY,FOG ,LH	NOT NECESSARY	910.20	-
1	BRACE SUB-ASSY ,FENDER APRON ,RH	TO REPAIR SEE LABOUR	282.70	-
1	APRON SUB-ASSY ,FRONT FENDER RH	TO REPAIR SEE LABOUR	944.20	-
1	FENDER SUB-ASSY ,FR ,LH	TO REPAIR SEE LABOUR	933.10	-
1	FENDER SUB-ASSY ,FR ,RH	TO REPAIR SEE LABOUR	933.10	-
1	HOOD SUB-ASSY	TO REPAIR SEE LABOUR	938.40	-
1	SUPPORT ,RADIATOR UPPER RH	TO REPAIR SEE LABOUR	76.70	-
			25,483.34	12,597.19

Report Ref No. CC3/CTI21007863/Ers3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF BRACE SUB-ASSY ,FENDER APRON ,RH ,APRON SUB-ASSY ,FRONT FENDER RH,FENDER SUB-ASSY ,FR ,LH ,FENDER SUB-ASSY ,FR ,RH, HOOD SUB-ASSY AND SUPPORT ,RADIATOR UPPER RH .		1,183.00	400.00
	SPRAY PAINT.		2,232.00	960.00
	TO REMOVE & REFIT DASH BOARD PANEL.		220.00	150.00
	TOWING CHARGE.		56.00	40.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO DO WHEEL ALIGNMENT /TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARDESS .		300.00	60.00
	TO REMOVE AND REFIX UNDERCARRIAGE.	NOT NECESSARY	300.00	-
	TO CHECK & RESET SYSTEM FUNCTION .		350.00	50.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			5,341.00	1,730.00
	GRAND TOTAL		30,824.34	14,327.19
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,800.00

Report Ref No. CC3/CTI21007863/Ers3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 5537E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 5537E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 5537E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

