



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 2568H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR RH DOOR HANDLE	BROKEN	48.00	48.00
1	REAR RH DOOR HANDLE SIDE COVER	NOT NECESSARY	20.00	-
1	REAR RH DOOR HANDLE INNER BACK BASE	BROKEN	43.00	43.00
1	REAR RH DOOR	BUCKLED	1,744.00	1,031.80
1	REAR RH DOOR GLASS OUTER MOULDING	NOT NECESSARY	46.00	-
1	REAR RH DOOR LOCK	NOT NECESSARY	268.00	-
	LESS 20% DISCOUNT		-433.80	-224.56
			1,735.20	898.24
1	REAR RH DOOR BLACK STICKER (SN)	NECESSARY	45.00	20.00
	LESS 20% DISCOUNT		-9.00	-
			36.00	20.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH DOOR BLACK STICKER (FRONT)(SN) (ADDITIONAL)	NECESSARY	45.00	20.00
1	REAR RH DOOR BLACK STICKER (REAR)(SN) (ADDITIONAL)	NECESSARY	45.00	20.00
			90.00	40.00
	<u>LABOUR</u>			
	TO REPAIR AFFECTED AREAS AND REPLACE REAR RH DOOR AND AFFECTED AREA.		500.00	250.00
	TO PUTTY AND RESPRAY REAR RH DOOR, DOOR HANDLE AND AFFECTED AREA.		500.00	250.00
	TO REMOVE AND REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR INTO NEW DOOR.		180.00	80.00
	CHECK LIGHTING AND WIRING.	NOT NECESSARY	50.00	-
			1,230.00	580.00
	GRAND TOTAL		3,091.20	1,538.24



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,230.00
---	--	--	-----------------

Report Ref No. CS/SMR21007867/Guf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.