

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21007868/VVF3E2

Date: 06/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700060261
Claimant Vehicle No : FBJ9198C Insured Vehicle No : SCG607C
Date of Loss: 12/07/2021 Nature of Claim: TP Claim No: 0628454098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ9198C**
Make & Model: HONDA CB400SF, 399cc Engine No: NC42E1201601
Reg. Date: 16/12/2014 (Man. Year: 2014) Chassis No: NC421601608
Colour: Red Odometer: 93446 km
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 160/60Z R17 Rear Tyre Size: 160/60Z R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/07/2021
Date Inspected: 28/07/2021 Inspected At: Equator Brotherhood (HQ)
25 Kaki Bukit Road 4
#03-19 Synergy @KB
Singapore 417800
Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$14,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
3	1		*FRONT WINDSHIELD	Cut	0.00 F	*- F
4	1		*FRONT WING MIRROR LH	Cut	0.00 F	*- F
5	1		*FRONT LH SIGNAL LAMP	Cut	0.00 F	*- F
6	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
7	1		*CLUTCH LEVER	Cut	0.00 F	*- F
8	1		*REAR FAIRING	Cut	0.00 F	*- F
9	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
10	1		*REAR FENDER MUDFLAP	Cut	0.00 F	*- F
11	1		*REAR RH SIGNAL LAMP	Bent	0.00 F	*- F
12	1		*REAR NUMBER PLATE	Dented	0.00 F	*- F
13	1		*REAR BOX	Cut	0.00 F	*- F
14	1		*LH CRASH BAR	Cut	0.00 F	*- F
15	1		*LH FAIRING RUBBER GARNISH	Cut	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >