

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG21007870/KGS3Q2

Date:

07/10/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070014421

Claimant Vehicle No : SNA964Y

Insured Vehicle No :

SJU3321A

Date of Loss: 19/07/2021

Nature of Claim:

TP

Claim No:

1062842328SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SNA964Y

Make &amp; Model:

TOYOTA COROLLA ALTIS, 1.8 (A)

Reg. Date:

01/06/2021 (Man. Year: 2021)

Colour:

Metallic Silver

Engine Capacity:

1797 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

Engine No:

2ZR2L07175

Chassis No:

ZWE2116062247

Odometer:

14929 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side:

Dunlop 9 mm

Rear Left Side:

Dunlop 9 mm

Front Right Side:

Dunlop 9 mm

Rear Right Side:

Dunlop 9 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

|                                          | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 5,784.90        | 2,409.85        | 3,375.05        | 58.34        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 2,080.00        | 1,200.00        | 880.00          | 42.31        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>7,864.90</b> | <b>3,609.85</b> | <b>4,255.05</b> | <b>54.10</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>3,050.00</b> |                 |              |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 7,864.90        | 3,050.00        | 4,814.90        | 61.22        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 550.54          | 213.50          | 337.04          | 61.22        |
| <b>Nett Amount (S\$)</b>                        | <b>8,415.44</b> | <b>3,263.50</b> | <b>5,151.94</b> | <b>61.22</b> |
| <b>+ Car Rental (3.0 x S\$120.00/day) (S\$)</b> |                 | 360.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>3,625.50</b> |                 |              |

INSPECTION

Date of Assignment: 23/07/2021

Date Inspected: 23/07/2021

Estimated Period of Repair: 4.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                | Condition     | Repairer's  | Amount       |
|-----|-----|----------|----------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID                   | Bent          | 1,678.00 FL | *839.50 FL   |
| 2   | 1   |          | *BOOTLID TOYOTA EMBLEM     | Necessary     | 110.00 FL   | *110.00 FL   |
| 3   | 1   |          | *BOOTLID COROLLA EMBLEM    | Necessary     | 95.00 FL    | *95.00 FL    |
| 4   | 1   |          | *BOOTLID HYBRID EMBLEM     | Necessary     | 100.00 FL   | *100.00 FL   |
| 5   | 1   |          | *BOOTLID LOCK              | Repair        | 458.20 FL   | *- FL        |
| 6   | 1   |          | *REAR BUMPER               | Bent          | 2,530.00 FL | *1,218.30 FL |
| 7   | 1   |          | *REAR LOWER BUMPER         | Dented        | 517.00 FL   | *517.00 FL   |
| 8   | 1   |          | *REAR SIDE RETAINER LH     | Serviceable   | 145.00 FL   | *- FL        |
| 9   | 1   |          | *REAR BUMPER REFLECTOR LH  | Serviceable   | 127.00 FL   | *- FL        |
| 10  | 1   |          | *END PANEL                 | Repair        | 1,188.00 FL | *- FL        |
| 11  | 1   |          | *END PANEL TOP COVER       | Serviceable   | 245.00 FL   | *- FL        |
| 12  | 1   |          | *REAR BUMPER CLIPS         | Necessary     | 100.00 FS   | *50.00 FS    |
| 13  | 1   |          | *END PANEL TOP COVER CLIPS | Not Necessary | 50.00 FS    | *- FS        |
| 14  | 1   |          | *REVERSE SENSORS           | Dented        | 240.00 FS   | *200.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>7,583.20</b> | <b>3,129.80</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | 1,798.30        | 719.95          |
| <b>Total Parts (S\$)</b>                                  | <b>5,784.90</b> | <b>2,409.85</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                          | Lab.Type | Repairer's      | Amount          |
|--------------------------------|----------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                      |          |                 |                 |
| 1                              | LABOUR CHARGES TO REPLACE ,REPAIR ,DISMANTLE AND REFIX ACCIDENT AREA | New      | 800.00          | 500.00          |
| 2                              | LABOUR CHARGES TO PAINT ON ACCIDENT AREA                             | New      | 1,000.00        | 600.00          |
| 3                              | TO CHECK AND RECTIFY ALL WIRING SYSTEM                               | New      | 60.00           | 20.00           |
| 4                              | TO REMOVE AND REFIT REVERSE SENSOR AND CONDUCT DISTANCE SETTING      | New      | 100.00          | 50.00           |
| 5                              | CAVITY TREATMENT AND APPLY SEALANT                                   | New      | 120.00          | 30.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                      |          | <b>2,080.00</b> | <b>1,200.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >