

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21007871/GVF3E2

Date: 26/08/2021

REFERENCE

Insured/Claimant: LUM YI LEONG LIONEL Policy No: MPC21P00057700
Date of Loss: 16/07/2021 Nature of Claim: OD Claim No: DMPC2100231H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX3308A**
Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491031269397
Reg. Date: 26/03/2018 (Man. Year: 2017) Chassis No: WDD2050402R371236
Colour: Grey Odometer: 48772 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$122,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,409.00	6,090.00	319.00	4.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	470.00	290.00	38.16
Paintwork Labour	380.00	320.00	60.00	15.79
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,549.00	6,880.00	669.00	8.86
+ GST 7.00/7.00% (S\$)	528.43	481.60	46.83	8.86
Nett Amount (S\$)	8,077.43	7,361.60	715.83	8.86

INSPECTION

Date of Assignment: 23/07/2021 Present Location: Vin's Motor Pte Ltd (Sin Ming)
Date Inspected: 23/07/2021 Inspected At: Vin's Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive, #03-03, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Aug 2021)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLX3308A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front RH headlamp (Order) (WCP)	Cracked	1,800.00 F	*1,800.00 F
2	1		*Front grille base (WCP)	Broken	70.00 F	*70.00 F
3	1		*Front grille housing (WCP)	Broken	70.00 F	*110.00 F
4	1		*Front grille emblem (WCP)	Cut	70.00 F	*70.00 F
5	1		*Front bumper (WCP)	Broken	880.00 F	*880.00 F
6	2		*Front bumper parking sensor @ \$100.00 (WCP)	Not Necessary	200.00 F	*- F
7	1		*Front bumper no.plate garnish (WCP)	Cracked	70.00 F	*70.00 F
8	1		*Front bumper centre lower grille (WCP)	Not Necessary	70.00 F	*- F
9	1		*Front bumper RH side retainer (WCP)	Not Necessary	50.00 F	*- F
10	1		*Front bumper LH side retainer (WCP)	Not Necessary	50.00 F	*- F
11	1		*Front bumper sponge (WCP)	Cracked	90.00 F	*90.00 F
12	1		*Front bumper reinforcement (WCP)	Bent	270.00 F	*270.00 F
13	1		*Front bumper air duct (WCP)	Deformed	30.00 F	*70.00 F
14	1		*Front bumper top beam (WCP)	Cracked	50.00 F	*50.00 F
15	10		*Front bumper clips @ \$4.00 (WCP)	Necessary	40.00 F	*40.00 F
16	1		*Front no.plate	Cracked	40.00 FS	*40.00 FS
<u>Supplementary #1</u>						
17	1		*Front LH headlamp (WCP)	Cracked	1,800.00 F	*1,800.00 F
18	1		*Front grille top chrome moulding - RH (WCP)	Cut	40.00 F	*40.00 F
19	1		*Front grille top chrome moulding - LH (WCP)	Cut	40.00 F	*40.00 F
20	1		*Front grille lower chrome - RH (WCP)	Cut	50.00 F	*50.00 F
21	1		*Front grille lower chrome - LH (WCP)	Cut	50.00 F	*50.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,830.00	5,540.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	579.00	550.00
Total Parts (\$\$)	6,409.00	6,090.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	380.00	320.00
<u>Labour Items</u>				
2	To reset front headlamp	New	280.00	150.00
3	To repair front damage	New	480.00	320.00
Gross Labour Cost (\$\$)			1,140.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >