



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 2014Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,055.20	-
1	FRONT BUMPER	DEFORMED	855.30	855.30
2	FRONT BUMPER SIDE RETAINER @\$62.40	NECESSARY	124.80	124.80
1	FRONT BUMPER LOWER GRILLE	CRACKED	192.20	192.20
2	FRONT BUMPER FOG LAMP GARNISH @\$88.30	O/S CUT	176.60	88.30
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	450.00	-
1	FRONT BUMPER REINFORCEMENT SPONGE	CRACKED	180.00	180.00
1	CENTRE GRILLE	CRACKED	750.00	750.00
1	CENTRE GRILLE CHROME	CRACKED	450.00	450.00
1	CENTRE GRILLE LOGO	NECESSARY	89.00	89.00
2	HEADLAMP @\$680.20	O/S CRACKED	1,360.40	680.20
1	SUPPORT PANEL	NOT NECESSARY	920.00	-
1	SUPPORT PANEL TOP COVER	NOT NECESSARY	188.20	-
	LESS 10% DISCOUNT		-	-340.98
			6,791.70	3,068.82
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET CENTRE GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
1	SET HEADLAMP CLIPS (SN)	NECESSARY	20.00	10.00
			110.00	100.00
<u>LABOUR</u>				
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET.		1,200.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	400.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.		100.00	30.00
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS & COMPRESSOR.	NOT NECESSARY	120.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	80.00	-
	RESET AIRBAG LIGHT.	NOT NECESSARY	250.00	-
			3,200.00	870.00
GRAND TOTAL			10,101.70	4,038.82

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00
--	--	--	--	----------

Report Ref No. CS/AGI21007872/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.