

ASS. REC. BY:

REF:

Kenneth

GRB / 210078761kb

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

30/7 83379.68 3379.88

7/8 83399.68 Car Ins

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

SLV 6473X

SLV 7858X

Yr Regn: 01, 18

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

SLV 6473X

SLV 7858X

Yr Regn: 01, 18

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0027572
Sing Moh Electrical Engineering Pte
Ltd

Page 1 of 2
Your ref. TP-SLM 7658X INDIA
Job No. 72152
Our ref. 21.07.13
Payment
Date 23/7/2021

Attn

Vehicle No SLV 6473X
Vehicle Model : Honda Vezel
Accident on ... 21/7/2021

Not Authorized

Recovery B4 pain

~~3374.88~~

~~3374.88~~

5 days

\$3,399.68

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear tailgate <i>953</i>	1,037.00	20.00	<i>B1</i> 829.60 ✓
1.00	Pc	Rear bumper <i>508.80</i>	553.10	20.00	<i>B1</i> 442.48 ✓
1.00	Pc	Rear bumper side RH	172.80	20.00	<i>B1</i> 138.24 ✓
4.00	Pcs	Rear bumper clips	3.50	20.00	<i>na</i> 11.20 ✓
1.00	Pc	Rear Vezel emblem	38.80	20.00	<i>na</i> 31.04 ✓
2.00	Pcs	Rear windscreen moulding	31.00	20.00	<i>na</i> 49.60 ✓
1.00	Pc	Rear end panel	452.40	20.00	<i>B1</i> 361.92 ✓
1.00	Pc	Rear end panel top cover	55.80	20.00	<i>na</i> 44.64 ✓
Special nett item:					
1.00	Set	Rear parking sensor with installation	200.00		<i>short</i> 200.00 ✓
Labour & Misc:					
1.00		To transfer rear camera	40.00		40.00 ✓
1.00		To remove + refix rear windscreen	140.00		140.00 <i>120</i>

SUPPLEMENTARY (PARTS)

1.00 Pc Rear fender arch garnish RH 172.10 ✓ NEC
1.00 Pc Rear tailgate weatherstrip 105.20 ✓ NEC

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0027572
Sing Moh Electrical Engineering Pte
Ltd

Page : 2 of 2
Your ref. : TP-SLM 7658X INDIA
Job No. : 72152
Our ref. : 21.07.13
Payment :
Date : 23/7/2021

Attn :

Vehicle No : SLV 6473X
Vehicle Model : Honda Vezel
Accident on : 21/7/2021

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To supply sealant	40.00		40.00 ✓
1.00		To straighten rear body, to knock dents on rear tyre panel and renew of parts 8.80	800.00		800.00 600L
1.00		To spray paint 853	700.00		700.00 450L

SUPPLEMENTARY (labour)

To dismantle + refix rear fender side trim LH, passenger seat, etc

60.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total
GST 7.00%
Total

3,828.72

268.01

4,096.73

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。

除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."