

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21007879/Utf3e2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623		Date:	18/08/2021	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	FBS 741X	Veh. Inspected		JSC 1804	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2102140/RUC	Excess (\$)		0.00	
	Assign From	MELVIN YE YONG KANG	Assign Date		23/07/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA 135LC	c.c		134	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	PMYUG0420H0075871	Colour		MULTI COLOUR	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	70/80-17	CORSA		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	70/80-17	CORSA		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS N/S BODY.	ELE SUSTAINED DAMAGES AT THE REAR PORTION, O/S AND				
5.	General Information					
	Accident Date	16/07/2021	Inspect Date / 1	Гime	23/07/2021 (03:15 PM)	
	Survey held at	BEAR'S GARAGE LLP				
		25 KAKI BUKIT ROAD 4 #03-62 SYNERGY@KB SINGAPORE 417800				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000					
	NOTE: REPAIRER	NOTE: REPAIRER NEVER ARRANGE FOR DISMANTLE STEP 2.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/SMO21007879/Utf3e2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE