

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007880/BQC2**Date:** 21/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00018932100

Claimant Vehicle No : SGY5577E **Insured Vehicle No :** YQ2156K

Date of Loss: 11/07/2021 Nature of Claim: TP Claim No: SNM21D203951/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY5577E**

Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: 2ARU366249

Reg. Date: 03/04/2017 (Man. Year: 2016) Chassis No: MR053AK5004011917

Colour: Grey Odometer: 0 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,249.80	9,995.37	2,254.43	18.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	2,440.00	1,590.00	39.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,279.80	12,435.37	3,844.43	23.61
Approved Total (Overridden) (\$\$)		9,950.00		
(\$\$)	16,279.80	9,950.00	6,329.80	38.88
+ GST 7.00/7.00% (\$\$)	1,139.59	696.50	443.09	38.88
Nett Amount (\$\$)	17,419.39	10,646.50	6,772.89	38.88

INSPECTION

Date of Assignment: 23/07/2021

Date Inspected: 23/07/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY5577E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*LH FRONT DOOR	Dented	1,210.30 FL	*1,210.30 FL
2	1	*LH FRONT DOOR FRAME BLACK TAPE	Necessary	78.40 FL	*59.60 FL
3	1	*LH FRONT DOOR OUTER CHROME MOULDING	Dented	145.60 FL	*145.60 FL
4	1	*LH REAR DOOR	Dented	1,112.13 FL	*1,112.13 FL
5	1	*LH REAR DOOR FRAME BLACK TAPE	Necessary	78.40 FL	*59.60 FL
6	1	*LH REAR DOOR OUTER CHROME MOULDING	Bent	145.60 FL	*145.60 FL
7	1	*LH REAR DOOR GLASS	Broken	748.00 FL	*275.40 FL
8	1	*LH REAR DOOR GLASS REGULATOR GEAR }	Bent	257.50 FL	*257.50 FL
9	1	*LH REAR DOOR GLASS REGULATOR GEAR MOTOR }	Bent	505.36 FL	*- FL
10	1	*LH REAR DOOR GLASS RUBBER CHANNEL	Necessary	81.00 FL	*81.00 FL
11	1	*LH REAR DOOR GLASS RUBBER CHANNEL GUIDE	Cut	157.30 FL	*157.30 FL
12	1	*LH REAR DOOR CHROME OUTER HANDLE	Cut	68.20 FL	*68.20 FL
13	1	*LH REAR DOOR CHROME OUTER HANDLE INNER BRACKET	Broken	155.61 FL	*155.61 FL
14	1	*LH REAR DOOR CHROME HANDLE SIDE COVER	Cut	35.80 FL	*35.80 FL
15	1	*LH REAR DOOR WEATHERSTRIP	Torn	205.30 FL	*175.00 FL
16	1	*LH REAR DOOR LOWER RUBBER SEAL	Necessary	55.40 FL	*55.40 FL
17	1	*LH REAR DOOR UPPER HINGE	Bent	81.40 FL	*81.40 FL
18	1	*LH REAR DOOR LOWER HINGE	Bent	81.40 FL	*81.40 FL
19	1	*LH REAR DOOR CHECKER	Bent	77.80 FL	*77.80 FL
20	1	*LH REAR DOOR LOCK	Jammed	408.90 FL	*333.30 FL
21	1	*LH REAR DOOR LOCK CATCH	Jammed	32.10 FL	*32.10 FL
22	1	*LH REAR DOOR SPEAKER	Not Damaged	185.44 FL	*- FL
23	1	*LH REAR DOOR INNER TRIM BOARD	Broken	758.90 FL	*758.90 FL
24	1	*LH REAR DOOR QUARTER GLASS RUBBER SEAL	Necessary	44.00 FL	*44.00 FL
25	1	*REAR WINDSCREEN GLASS RUBBER MOULDING	Necessary	111.01 FL	*111.01 FL
26	1	*LH REAR FENDER	Dented	973.82 FL	*973.82 FL
27	1	*LH REAR FENDER SPLASH SHIELD	Broken	137.17 FL	*137.17 FL
28	1	*LH SIDE ROCKER PANEL GARNISH	Dented	438.60 FL	*438.60 FL
29	1	*LH REAR SPORT RIM (ORIGINAL)	Broken	945.85 FL	*945.85 FL
30	1	*LH REAR KNUCKLE ARM	Broken	547.77 FL	*308.00 FL
31	1	*LH REAR WHEEL BEARING	Jammed	249.00 FL	*135.00 FL
32	1	*LH REAR SHOCK ABSORBER	Bent	347.10 FL	*278.50 FL
33	1	*LH REAR UPPER ADJUSTABLE ARM	Bent	181.00 FL	*181.00 FL
34	1	*LH REAR LOWER ARM	Bent	428.05 FL	*394.00 FL
35	1	*LH REAR CONTROL ARM	Bent	162.80 FL	*162.80 FL
36	1	*LH REAR STABILIZER BAR LINKAGE	Bent	73.18 FL	*73.18 FL
37	1	*RH REAR SPORT RIM (ORIGINAL)	Broken	945.85 FL	*945.85 FL
38	1	*RH REAR KNUCKLE ARM	Broken	547.77 FL	*308.00 FL
39	1	*RH REAR WHEEL BEARING	Jammed	249.00 FL	*135.00 FL
40	1	*RH REAR SHOCK ABSORBER	Bent	347.10 FL	*278.50 FL
41	1	*RH REAR UPPER ADJUSTABLE ARM	Bent	181.00 FL	*181.00 FL
42	1	*RH REAR LOWER ARM	Bent	428.05 FL	*394.50 FL
43	1	*RH REAR CONTROL ARM	Bent	162.80 FL	*162.80 FL
44	1	*RH REAR STABILIZER BAR LINKAGE	Bent	73.18 FL	*73.18 FL
45	1	*REAR BUMPER	Cut	639.80 FL	*639.80 FL
46	1	*SET LH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

9/21/21, 2:08 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET LH REAR DOOR INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*30.00 FS
48	1		*LH REAR DOOR GLASS SOLAR FILM	Necessary	280.00 FS	*60.00 FS
49	1		*LH REAR TYRE	Broken	350.00 FS	*250.00 FS
50	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
51	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
52	1		*LH REAR FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
53	1		*SET LH REAR FENDER INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*30.00 FS
54	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,969.74	13,160.50
- List Item Discount on L Items 25.00/25.00% (S\$)					3,719.94	3,165.13
Total Parts (S\$)					12,249.80	9,995.37
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,100.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE AND REPLACE LH FRONT DOOR INNER PARTS TO NEW DOOR	New	100.00	60.00
6	REMOVE AND REPLACE LH REAR DOOR INNER PARTS TO NEW DOOR	New	100.00	60.00
7	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
8	REMOVE AND REINSTALL REAR INNER TRIMS,GARNISH,BOARDS,ROOF LINING,SEATS AND MAT TO ASSIST REPAIR	New	380.00	120.00
9	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	60.00
10	REMOVE AND REPLACE LH REAR UNDERCARRIAGE PARTS	New	250.00	180.00
11	REMOVE AND REPLACE RH REAR UNDERCARRIAGE PARTS	New	250.00	180.00
12	REMOVE AND REINSTALL FUEL TANK,PIPES,HOSES AND ALL ATTACHMENTS TO ASSIST REPAIR	New	120.00	0.00
13	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	70.00	60.00
Gross Labour Cost (\$)			4,030.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >