

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007882/KPA3Q2
Date: 19/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993555
Claimant Vehicle No :	SHD15S	Insured Vehicle No :	SMX8265U
Date of Loss:	19/07/2021	Nature of Claim:	TP
		Claim No:	8898006161SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD15S		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002527
Reg. Date:	02/10/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC281655
Colour:	Metallic White/Red	Odometer:	658113 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,929.20	12,421.02	6,508.18	34.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	3,520.00	4,060.00	53.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,509.20	15,941.02	10,568.18	39.87
Approved Total (Overridden) (S\$)		8,650.00		

(S\$)	26,509.20	8,650.00	17,859.20	67.37
+ GST 7.00/7.00% (S\$)	1,855.64	605.50	1,250.14	67.37
Nett Amount (S\$)	28,364.84	9,255.50	19,109.34	67.37
+ Car Rental (13.0 x S\$81.13/day) (S\$)		1,054.69		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,317.64		
Global Sum Settlement (S\$)		10,300.00		

INSPECTION

Date of Assignment: 22/07/2021

Date Inspected: 22/07/2021

Estimated Period of Repair: 11.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*HEADLAMP LH	Mtg Cracked	743.60 FL	*743.60 FL
3	1		*FENDER PANEL FRT LH	Repair	437.10 FL	*- FL
4	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
5	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
6	1		*FRAME FULL SUPPORT PANEL	Cracked	592.70 FL	*592.70 FL
7	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
8	1		*BUMPER LOWER REAR	Cracked	411.90 FL	*411.90 FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
10	1		*BUMPER REFLECTOR RH	Broken	16.60 FL	*16.60 FL
11	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
12	1		*BUMPER BRACKET SIDE RH REAR	Distorted	82.10 FL	*82.10 FL
13	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
14	1		*BUMPER BRACKET SIDE LH REAR	Distorted	80.80 FL	*80.80 FL
15	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
16	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
17	1		*BUMPER BEAM BRACJKET LH REAR	Repair	114.50 FL	*- FL
18	1		*BUMPER BEAM BRACJKET RH REAR	Bent	114.50 FL	*114.50 FL
19	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
20	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
21	1		*FENDER PANEL REAR RH	Buckled	1,933.20 FL	*1,933.20 FL
22	1		*WHEELARCH REAR RH	Distorted	275.40 FL	*275.40 FL
23	1		*TAILLAMP RH	Cracked	401.40 FL	*401.40 FL
24	1		*EXHAUST REAR	Bent	4,737.24 FS	*3,200.00 FS
25	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
26	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
27	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
28	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	*277.70 FL
29	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
30	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
31	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
32	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
33	1		*BOOT LOCK	Repair	246.60 FL	*- FL
34	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
35	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FR BUMPER CLIP	Necessary	65.00 FS	*65.00 FS
37	1		*RADIATOR GRILLE CLIP	Not Necessary	60.00 FS	*- FS
38	1		*FENDER CLIP	Not Necessary	70.00 FS	*- FS
39	1		*SET PARKING AID	Dented	700.00 FS	*400.00 FS
40	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
41	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
42	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
43	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
44	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
45	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
46	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
47	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
48	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
49	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
50	1		*LICENSE PLATE WITH HOLDER FRT	Dented	120.00 FS	*45.00 FS
51	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
52	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
53	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,295.22	13,359.80
- List Item Discount on L Items 10.00/10.00% (S\$)	1,366.02	938.78
Total Parts (S\$)	18,929.20	12,421.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	1,540.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	1,500.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	120.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	80.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE}	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	40.00
Gross Labour Cost (S\$)			7,580.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >