

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007891/AQCN2**Date:** 23/08/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00117192000

Claimant Vehicle No : SMP4226B**Insured Vehicle No :** XD6156P

Date of Loss: 21/07/2021

Nature of Claim: TP

Claim No: SNM21D204040/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMP4226B**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FGKU190786

Reg. Date: 26/09/2019 (Man. Year: 2019)

Chassis No: KMHD841CMLU964138

Colour: Black

Odometer: 101041 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,594.70	3,117.76	3,476.94	52.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,640.00	1,540.00	48.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,774.70	4,757.76	5,016.94	51.33
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	9,774.70	3,800.00	5,974.70	61.12

INSPECTION

Date of Assignment: 27/07/2021

Date Inspected: 23/07/2021 Inspected At:

 Automobile Hub Enterprise
 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @
 KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP4226B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	459.40 F	*459.40 FL
2	1		*REAR BUMPER SIDE HOLDER RH	Damaged	29.40 F	*29.40 FL
3	1		*REAR BUMPER REFLECTOR RH	Cracked	201.50 F	*201.50 FL
4	1		*TAILLAMP RH	Cracked	758.60 F	*758.60 FL
5	1		*TAILLAMP PANEL RH	Repair	386.20 F	*- FL
6	1		*REAR RH FENDER	Distorted	1,892.00 F	*1,892.00 FL
7	1		*REAR RH FENDER INNER SHIELD	Deformed	120.20 F	*120.20 FL
8	1		*REAR RH FENDER INNER TRIM	Not Necessary	279.80 F	*- FL
9	1		*REAR RH FENDER INNER PANEL	Repair	899.00 F	*- FL
10	1		*REAR RH FENDER AIR VENT	Deformed	98.50 F	*98.50 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	135.00 F	*135.00 FL
12	1		*REAR RH MUDFLAP	Deformed	65.10 F	*65.10 FL
13	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	20.00 FS	*20.00 FS
15	1		*REAR RH FENDER INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
16	1		*REAR RH WHEEL RIM	Not Necessary	850.00 FS	*- FS
17	1		*REAR RH TYRE	Not Necessary	280.00 FS	*- FS
18	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,594.70	3,869.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	751.94
Total Parts (\$\$)	6,594.70	3,117.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	700.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
8	TO SPRAY TUFF COAT	New	150.00	80.00
Gross Labour Cost (\$)			3,180.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >