

TP China.
Xiao Chen.

SMP4226B.

Hyundai Avante.

KMHD841CMLU 964138

Rear Bumper	Distorted	459.40 /
Rear Bumper clips.	M	30(SW) /
Rear Bumper Side Holder RH.	2nd	29.40 /
Rear Bumper Reflector RH	Painted	201.50 /
Taillamp RH.	Painted	758.60 /
Taillamp Panel RH.	Rear	386.20 X
Rear RH Fender	Distorted	1892 /
Rear RH Fender Inner Shield	Reh	120.20 /
Rear RH Fender Inner Shield clips.	M	20(SW) /
Rear RH Fender Inner Trim.	2nd	279.80 X
Rear RH Fender Inner Trim clips	M	30(SW) X
Rear RH Fender Inner Panel.	Rear	899 X
Rear RH Fender Air Vant.	Reh	98.50 /
Rear RH Wheel Rim.	M	850(SW) X
Rear RH Tyre.	M	289(SW) X.

SMP 4226B.

Rear Windscreen moulding } 135 ✓
Rear Windscreen Sealant. } 60(SN) ✓
Rear RH Mudflap Rehd } 65.10 ✓
3759.70 SN: 110
3007.76

Panel Beating

Spray Painting.

Wiring.

To remove cruise sensor

To remove upholstery.

To remove rear windscreen.

To perform wheel alignment.

To spray tuft coat

~~1200~~ 600

~~1200~~ 700

~~50~~ 30

~~100~~ 50

~~150~~ 60

~~180~~ 120

150 +

~~150~~ 80

Wheel: 4757.76

4/s: 3.8K.

0.5 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: