

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21007892/BES3Q2
Date: 26/08/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SKL998C	Insured Vehicle No :	SLP6949Y
Date of Loss:	20/07/2021	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL998C	Engine No:	2AZG226986
Make & Model:	TOYOTA VELLFIRE, 2.5 CVT (A)	Chassis No:	ANH208292600
Reg. Date:	01/11/2013 (Man. Year: 2013)	Odometer:	187570 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,313.84	5,684.50	7,629.34	57.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	1,590.00	2,700.00	62.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,603.84	7,274.50	10,329.34	58.68
Approved Total (Overridden) (S\$)		5,800.00		

(S\$)	17,603.84	5,800.00	11,803.84	67.05
+ GST 7.00/7.00% (S\$)	1,232.27	406.00	826.27	67.05
Nett Amount (S\$)	18,836.11	6,206.00	12,630.11	67.05
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 23/07/2021

Date Inspected: 26/07/2021

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL998C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,575.80 FL	*1,379.00 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Necessary	121.35 FL	*72.30 FL
3	1		*REAR BUMPER RH UPPER COVER	Broken	181.00 FL	*181.00 FL
4	1		*REAR BUMPER RH UPPER COVER RETAINER	Necessary	113.00 FL	*72.30 FL
5	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Damaged	178.00 FL	*- FL
6	4		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	172.40 FL	*160.00 FL
7	1		*REAR BUMPER RH SPLASH SHIELD	Broken	87.30 FL	*87.30 FL
8	1		*RH TAILLAMP ASSY	Broken	560.80 FL	*560.80 FL
9	1		*REAR RH FENDER	Dented	1,566.40 FL	*1,355.10 FL
10	1		*REAR RH FENDER INNER TRIM BOARD	Broken	1,396.60 FL	*848.10 FL
11	1		*REAR RH SPORT RIM (ORIGINAL)	Not Damaged	2,332.00 FL	*- FL
12	1		*REAR RH WHEEL BEARING	Not Damaged	923.30 FL	*- FL
13	1		*REAR RH SHOCK ABSORBER	Not Damaged	454.90 FL	*- FL
14	1		*REAR AXLE BEAM	Not Damaged	2,838.90 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
16	1		*SET REAR BUMPER RH UPPER COVER CLIPS	Necessary	50.00 FS	*20.00 FS
17	1		*REAR RH FENDER GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
18	1		*REAR RH FENDER GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
19	1		*REAR RH FENDER JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
20	1		*REAR RH TYRE	Not Damaged	450.00 FS	*- FS
21	1		*BRAKE FLUID	Not Necessary	50.00 FS	*- FS
22	1		*RH REAR FENDER INNER AIRCON EVAPORATOR UNIT	Broken	4,156.70 FL	*2,650.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,478.45	7,526.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,164.61	1,841.50
Total Parts (\$\$)	13,313.84	5,684.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS TO PANEL BEATING ,CUT /WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	500.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	40.00
5	REMOVE ,REFIT AND REPLACE REAR INNER TRIMS ,GARNISH AND BOARDS TO ASSIST REPAIR	New	280.00	150.00
6	REMOVE AND REFIT REAR RH FENDER GLASS TO ASSIST REPAIR	New	200.00	120.00
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS AND WIRE HARNESS TO ASSIST REPAIR	New	100.00	60.00
8	REMOVE AND REFIT ROOF TOP LINING ,CAR MAT AND SEATS TO ASSIST REPAIR	New	450.00	0.00
9	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
10	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	400.00	0.00
11	PERFORM BRAKE BLEEDING SYSTEM AND CHECK FOR LEAKAGE	New	80.00	0.00
12	REMOVE AND REPLACE RH REAR FENDER AIRCON EVAPORATOR UNIT TO ASSIST REPAIR TO REFILL AIRCON GAS	New	300.00	120.00
Gross Labour Cost (\$\$)			4,290.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >