

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007896/EGS3Q2**Date:** 12/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100157200
<b>Claimant Vehicle No :</b>	GBK1883E	<b>Insured Vehicle No :</b>	GT3333G
Date of Loss:	02/07/2021	Nature of Claim:	TP
		Claim No:	9831578423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBK1883E</b>	Engine No:	1KDB018399
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P800249982
Reg. Date:	31/01/2020 (Man. Year: 2019)	Odometer:	22646 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R15C	Rear Tyre Size:	185 R15C
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,867.57	3,684.27	4,183.30	53.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,460.00	1,940.00	57.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,267.57</b>	<b>5,144.27</b>	<b>6,123.30</b>	<b>54.34</b>
<b>+ GST 7.00/7.00% (S\$)</b>	788.73	360.10	428.63	54.34
<b>Nett Amount (S\$)</b>	<b>12,056.30</b>	<b>5,504.37</b>	<b>6,551.93</b>	<b>54.34</b>
<b>+ Loss of Use (5.0 x S\$90.00/day) (S\$)</b>		450.00		
	<b>Nett Liability (S\$)</b>	<b>5,954.37</b>		

INSPECTION

Date of Assignment:	23/07/2021	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Date Inspected:	23/07/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	420.00 FL	*420.00 FL
2	2		*REAR BUMPER RETAINER LH/RH	Not Necessary	168.00 FL	*- FL
3	2		*REAR BUMPER UPPER COVER LH/RH	Not Necessary	216.00 FL	*- FL
4	2		*REAR BUMPER UPPER COVER RETAINER LH/RH	Not Necessary	168.00 FL	*- FL
5	4		*REAR BUMPER CENTER BRACKET	Not Necessary	192.00 FL	*- FL
6	1		*SPARE WHEEL CARRIER	Not Necessary	280.00 FL	*- FL
7	1		*REAR END PANEL OUTER	Repair	330.00 FL	*- FL
8	1		*TAILGATE	Dented	2,162.70 FL	*2,162.70 FL
9	1		*TAILGATE LOCK	Jammed	250.00 FL	*250.00 FL
10	1		*TAILGATE WEATHERSTRIP	Torn	408.40 FL	*408.40 FL
11	1		*TAILGATE GARNISH	Crushed	170.00 FL	*170.00 FL
12	1		*TAILGATE GARNISH PROTECTOR	Not Necessary	15.00 FL	*- FL
13	1		*TAILGATE INNER TRIM BOARD	Not Necessary	264.00 FL	*- FL
14	1		*TAILGATE LOGO	Necessary	72.20 FL	*72.20 FL
15	1		*TAILGATE EMBLEM HIACE	Necessary	51.40 FL	*51.40 FL
16	2		*TAIL LAMP LH/RH	Not Necessary	711.40 FL	*- FL
17	1		*REAR WINDSCREEN GLASS	Broken	1,191.00 FL	*1,191.00 FL
18	1		*REAR WIPER ARM	Not Necessary	95.00 FL	*- FL
19	1		*THIRD BRAKE LIGHT	Not Necessary	195.00 FL	*- FL
20	2		*TAILGATE HINGE LH/RH	Not Necessary	120.00 FL	*- FL
21	2		*TAILGATE STAY LH/RH	Not Necessary	560.00 FL	*- FL
22	1		*EXHAUST SILENCER	Not Necessary	470.00 FL	*- FL
23	1		*REAR WIPER ASSY	Not Necessary	950.00 FL	*- FL
24	2		*LICENSE PLATE LIGHT	Not Necessary	210.00 FL	*- FL
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
27	1		*70KM/H STICKER	Necessary	30.00 FS	*20.00 FS
28	2		*SEALANT	Necessary (1 PCS ONLY)	160.00 FS	*40.00 FS
29	1		*PAN PACIFIC METAL PLATE	Necessary	80.00 FS	*50.00 FS
30	1		*REAR NO .PLATE	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,285.10</b>	<b>4,865.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,417.53	1,181.43
<b>Total Parts (\$)</b>	<b>7,867.57</b>	<b>3,684.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CUT /WELD ,PANEL BEAT & ALIGN REAR PORTION ,TO REMOVE & REPLACE DAMAGED PARTS	New	1,500.00	600.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	30.00
5	TO REMOVE & REFIT SPARE TYRE INTERIOR TRIMS TO FACILITATE REPAIR	New	100.00	0.00
6	TO PUTTY ,SPRAY PAINTING REAR PORTIONS & OTHER AFFECTED AREAS	New	1,200.00	600.00
7	TO TRANSFER TAILGATE COMPONENTS TO NEW TAILGATE	New	100.00	50.00
8	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORKLOAD	New	100.00	0.00
9	TO REMOVE & REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
			<b>Gross Labour Cost (\$)</b>	<b>3,400.00</b>
				<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >