

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

DATE : 22 JUL 2021
CLAIM TYPE : TP CLAIM
D.O.A : 02 JUL 2021

VEHICLE NO : GBK1883E
MAKE & MODEL : TOYOTA HIACE VAN TURBO 5DR MT
CHASSIS NO : JTFHT02P800249982

TO : AIG

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER / DD		\$ 420.00	\$ 420.00
2	2	REAR BUMPER RETAINER LH/RH X BR NN		\$ 84.00	\$ 168.00
3	2	REAR BUMPER UPPER COVER LH/RH X NN		\$ 108.00	\$ 216.00
4	2	REAR BUMPER UPPER COVER RETAINER LH/RH X NN		\$ 84.00	\$ 168.00
5	4	REAR BUMPER CENTER BRACKET X NN		\$ 48.00	\$ 192.00
6	1	SPARE WHEEL CARRIER X NN		\$ 280.00	\$ 280.00
7	1	REAR END PANEL OUTER X R		\$ 330.00	\$ 330.00
8	1	TAILGATE / DD		\$ 2,162.70	\$ 2,162.70
9	1	TAILGATE LOCK / Damaged		\$ 250.00	\$ 250.00
10	1	TAILGATE WEATHERSTRIP / TN		\$ 408.40	\$ 408.40
11	1	TAILGATE GARNISH / CR4		\$ 170.00	\$ 170.00
12	1	TAILGATE GARNISH PROTECTOR X NN		\$ 15.00	\$ 15.00
13	1	TAILGATE INNER TRIM BOARD X NN		\$ 264.00	\$ 264.00
14	1	TAILGATE LOGO / NCC		\$ 72.20	\$ 72.20
15	1	TAILGATE EMBLEM "HIACE" / NCC		\$ 51.40	\$ 51.40
16	2	TAIL LAMP LH/RH X NN		\$ 355.70	\$ 711.40
17	1	REAR WINDSCREEN GLASS / BR		\$ 1,191.00	\$ 1,191.00
18	1	REAR WIPER ARM X NN		\$ 95.00	\$ 95.00
19	1	THIRD BRAKE LIGHT X NN		\$ 195.00	\$ 195.00
20	2	TAILGATE HINGE LH/RH X NN		\$ 60.00	\$ 120.00
21	2	TAILGATE STAY LH/RH X NN		\$ 280.00	\$ 560.00
22	1	EXHAUST SILENCER X NN		\$ 470.00	\$ 470.00
23	1	REAR WIPER ASSY X NN		\$ 950.00	\$ 950.00
24	2	LICENSE PLATE LIGHT (LH) X BR NN		\$ 105.00	\$ 210.00
				\$ 8,449.40	\$ 9,670.10

4725-70
-25%
3544-27

TOTAL PRICE	\$ 9,670.10
LESS 25%	\$ 2,417.53
SUB TOTAL PRICE	\$ 7,252.58

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIP SET / NCC		\$ 50.00	\$ 50.00
2	1	REVERSE SENSOR X NN		\$ 250.00	\$ 250.00
3	1	70KM/H STICKER / NCC		\$ 30.00	\$ 30.00
4	2	SEALANT / NCC		\$ 80.00	\$ 160.00
5	1	PAN PACIFIC METAL PLATE / NCC		\$ 80.00	\$ 80.00
6	1	REAR NO. PLATE X AA		\$ 45.00	\$ 45.00
TOTAL S/NETT				\$ 535.00	\$ 615.00

Labour Charges

1	To cut/weld, panel beat & align Rear portion, to remove & replace damaged parts.	\$ 1,500.00	600
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 50.00	30
4	To remove & replace reverse sensor.	\$ 100.00	30

5	To remove & refit spare tyre, interior trims to facilitate the repair.	\$	100.00	X
6	To putty, spray painting Rear Portions & other affected areas.	\$	1,200.00	600
7	To transfer tailgate components to new tailgate.	\$	100.00	50
8	To remove & refit exhaust system to assist workload.	\$	100.00	X
9	To remove & refit rear windscreen glass.	\$	150.00	120

TOTAL LABOUR

1460

\$ 3,400.00

Total Cost of Repairs

\$ 11,032.00

(Total parts + Total S/Nett + Total Labour Cost)

P- 3544.27

M- 149

L- 1460

5144.27

Stev CLKK)

23/7/21, 10:00am

WZ AL

P/P

My Bal sy

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: