

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007897/AUCN2**Date:** 12/10/2021**REFERENCE**

Insured/Claimant:	PREMIUM AUTOMOBILES PTE LTD	Policy No:	0999993555
Date of Loss:	19/07/2021	Nature of Claim:	OD Claim No: 8898006161SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8265U	Engine No:	CHZC33563
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V4KA122033
Reg. Date:	30/01/2021 (Man. Year: 2019)	Odometer:	9796 km
Colour:	Red		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,048.00	13,220.12	16,827.88	56.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,744.00	7,244.00	8,500.00	53.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,792.00	20,464.12	25,327.88	55.31
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	44,292.00	18,964.12	25,327.88	57.18
+ GST 7.00/7.00% (S\$)	3,100.44	1,327.49	1,772.95	57.18
Nett Amount (S\$)	47,392.44	20,291.61	27,100.83	57.18

INSPECTION

Date of Assignment:	26/07/2021		
Date Inspected:	22/07/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION LH	Damaged	39.00 FS	*30.48 FS
4	1		*FRONT BUMPER GRILLE CENTRE	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	536.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT LH	Damaged	296.00 FS	*237.20 FS
7	1		*FRONT BUMPER COVER TRIM LH	Not Necessary	163.00 FS	*- FS
8	1		*FRONT ADAPTER WHEEL HOUSING LINER LH	Not Necessary	38.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	1,406.00 FS	*- FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	191.00 FS	*- FS
11	1		*FRONT AIR GUIDE GRILLE LH	Cut	188.00 FS	*150.00 FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	795.00 FS	*- FS
13	1		*FRONT FOAM FILLER PIECE	Cracked	189.00 FS	*151.20 FS
14	1		*FRONT REINFORCEMENT COVER	Not Necessary	122.00 FS	*- FS
15	1		*STICKER FOR AIR CONDITIONER	Not Necessary	8.00 FS	*- FS
16	1		*STICKER FOR SIGN CAUTION	Not Necessary	14.00 FS	*- FS
17	1		*SIGNAL HORN LH	Damaged	200.00 FS	*159.60 FS
18	1		*FRONT FENDER LH	Distorted	851.00 FS	*680.40 FS
19	1		*FRONT FENDER ATTACHMENT PARTS LH	Not Necessary	72.00 FS	*- FS
20	1		*FRONT FENDER BRACKET LH CENTRE	Distorted	39.00 FS	*30.72 FS
21	1		*FRONT FENDER POP RIVET	Necessary	17.00 FS	*13.20 FS
			(5 Pcs)			
22	1		*FRONT FENDER BRACE LH	Bent	96.00 FS	*76.48 FS
23	1		*FRONT FENDER BRACKET LH	Damaged	28.00 FS	*21.84 FS
24	1		*FRONT FENDER CLOSING ELEMENT LH	Not Necessary	33.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER LH	Torn	169.00 FS	*134.80 FS
26	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS LH	Not Necessary	89.00 FS	*- FS
27	1		*BONNET	Dented	3,134.00 FS	*2,507.20 FS
28	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
29	2		*BONNET HINGE LH/RH	Not Necessary	124.00 FS	*- FS
30	1		*BONNET SAFETY CATCH	Not Necessary	90.00 FS	*- FS
31	1		*BONNET STRIKER LH	Not Necessary	110.00 FS	*- FS
32	1		*BONNET SIDE SEAL LH	Necessary	41.00 FS	*32.48 FS
33	1		*BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS
34	1		*BONNET LID LOCK WITH SWITCH	Not Necessary	214.00 FS	*- FS
35	1		*BONNET NOISE INSULATION	Not Necessary	219.00 FS	*- FS
36	1		*PLENUM CHAMBER COVER	Not Necessary	179.00 FS	*- FS
37	1		*LED HEADLIGHT LH	Cracked	5,455.00 FS	*4,364.00 FS
38	1		*LED WITH HEAT SINK LH	Not Necessary	733.00 FS	*- FS
39	1		*LED HEADLIGHT POWER MODULE LH	Not Necessary	758.00 FS	*- FS
40	1		*LED HEADLIGHT CONTROL UNIT	Not Necessary	557.00 FS	*- FS
41	1		*LED HEADLIGHT HOSE LH	Not Necessary	40.00 FS	*- FS
42	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	Damaged	142.00 FS	*113.60 FS
43	1		*HOSE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	68.00 FS	*- FS
44	1		*PUMP FOR HEADLIGHT WASHER SYSTEM	Not Necessary	155.00 FS	*- FS
45	1		*PUMP FOR WINDSCREEN WASHER SYSTEM	Not Necessary	125.00 FS	*- FS
46	1		*WASHER WATER RESERVOIR	Deformed	206.00 FS	*164.40 FS
47	1		*FRONT LOCK CARRIER	Not Necessary	727.00 FS	*- FS
48	6		*RADIATOR COOLANT	Not Necessary	266.00 FS	*- FS
49	1		*RADIATOR AIR GUIDE LH	Not Necessary	25.00 FS	*- FS
50	1		*FRONT DOOR LH	Repair	3,039.00 FS	*- FS
51	1		*FRONT DOOR OUTER SEAL LH	Not Necessary	161.00 FS	*- FS
52	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
53	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
54	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
55	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	241.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT DOOR CATCH LH	Not Necessary	105.00 FS	*- FS
57	1		*FRONT WINDOW SLOT SEAL LH	Not Necessary	309.00 FS	*- FS
58	1		*FRONT ALUMINIUM RIM LH	Cut	1,166.00 FS	*932.80 FS
59	1		*FRONT CONTROL ARM LH	Bent	373.00 FS	*298.00 FS
60	1		*STABILIZER BAR	Not Necessary	395.00 FS	*- FS
61	1		*FRONT WHEEL BEARING LH	Damaged	579.00 FS	*462.80 FS
62	1		*FRONT WHEEL BEARING HUB LH	Damaged	478.00 FS	*382.40 FS
63	1		*FRONT GUIDE JOINT LH	Bent	124.00 FS	*98.80 FS
64	1		*COUPLING ROD	Not Necessary	98.00 FS	*- FS
65	1		*FRONT GAS SHOCK ABSORBER LH	Not Necessary	259.00 FS	*- FS
66	1		*FRONT TRACK ROD	Bent	92.00 FS	*73.04 FS
67	1		*TIRE ROD END LH	Bent	122.00 FS	*97.20 FS
68	1		*FRONT TYRE LH	Punctured	285.00 FS	*285.00 FS
69	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
70	1		*SUNDRIES	Necessary	500.00 FS	*110.88 FS
71	1		*BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
					Total Parts (S\$)	30,048.00 13,220.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
4	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	350.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET,LHS FRONT DOOR AND LHS HEADLIGHT,TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,600.00	1,500.00
6	TO RESPRAY FRONT BUMPER,BONNET,LHS FRONT FENDER,HINGES,LHS UPPER A-PILLAR AND LHS FRONT DOOR	New	4,700.00	2,750.00
7	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY	New	1,800.00	1,800.00
8	TO RENEW LHS FRONT RIM WITH TYRE.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
9	TO TOW BACK VEHICLE BACK FROM ACCIDENT SCENE	New	280.00	0.00
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			15,744.00	7,244.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >