

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21007898/KUF3E2

Date: 02/12/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001714823

Claimant Vehicle No : SJY9825C

Insured Vehicle No : SMZ1579A

Date of Loss: 23/07/2021

Nature of Claim: TP

Claim No: 260362

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY9825C**

Make & Model: TOYOTA WISH, 2.0 (A)

Engine No: 3ZRA517300

Reg. Date: 20/10/2010 (Man. Year: 2010)

Chassis No: JTDGJ20W805003212

Colour: Metallic Black

Odometer: 380345 km

Engine Capacity: 1987 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,968.75	9,325.35	5,643.40	37.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	2,030.00	2,480.00	54.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,478.75	11,355.35	8,123.40	41.70
Approved Total (Overridden) (S\$)		9,050.00		
Nett Amount (S\$)	19,478.75	9,050.00	10,428.75	53.54

INSPECTION

Date of Assignment: 26/07/2021

Date Inspected: 26/07/2021 Inspected At:

Blk 1 Sin Ming Industrial Sector C #01-135.

Repairer: A T Auto Consultant (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2021)
Parts:	M1-MPV	TOYOTA WISH 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY9825C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	532.00 FL	*532.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/S Cracked	121.00 FL	*61.00 FL
3	1		*FRONT BUMPER LOWER GRILLE RH	Serviceable	51.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER RH	Serviceable	95.00 FL	*- FL
5	1		*RADIATOR LOWER COVER	Cracked	186.00 FL	*186.00 FL
6	2		*HEAD LAMP RH / LH	O/S Cut / N/S Broken	1,986.00 FL	*1,344.00 FL
7	1		*WIPER TANK	Dented	205.00 FL	*205.00 FL
8	1		*FRONT FENDER RH / LH	O/S Repair / N/S Bent	1,778.00 FL	*786.90 FL
9	1		*FRONT FENDER INNER GARNISH LH	Cracked	165.00 FL	*165.00 FL
10	1		*FRONT WHEEL ARCH GARNISH RH / LH	N/S Cracked	372.00 FL	*186.00 FL
11	1		*FRONT WHEEL INNER GANNISH LH	Repeated	165.00 FL	*- FL
12	1		*FRONT PILLAR OUTER LH	Repair	698.00 FL	*- FL
13	1		*FRONT WHEEL HUB PANEL LH	Repair	0.00 FL	*- FL
14	1		(NPA) *BONNET	Repair	0.00 FL	*- FL
15	1		(NPA) *FRONT DOOR LH	Repair	0.00 FL	*- FL
16	1		*ROCKER PANEL GARNISH LH	Deformed / Cracked	506.00 FL	*506.00 FL
17	1		*FRONT SUPPORT PANEL	Repair	1,365.00 FL	*- FL
18	1		*CROSS MEMBER CENTER	Bent	1,860.00 FL	*1,454.20 FL
19	1		*CROSS MEMBER FRONT	Repair	465.00 FL	*- FL
20	1		*ENGINE MOUNTING FRONT	Distorted	168.00 FL	*168.00 FL
21	1		*ENGINE MOUNTING REAR	Distorted / Cracked	221.00 FL	*221.00 FL
22	1		*STEERING RACK	Bent / Jammed	1,623.00 FL	*1,623.00 FL
23	1		*TIE ROD END LH	Bent	145.00 FL	*145.00 FL
24	1		*STABILIZER BAR	Bent	428.00 FL	*328.00 FL
25	1		*STABILIZER BAR LINKAGE LH	Distorted	213.00 FL	*213.00 FL
26	1		*DRIVER SHAFT	Bent	1,425.00 FL	*1,258.70 FL
27	1		*ABSORBER LH	Bent	412.00 FL	*412.00 FL
28	1		*ABSORBER MOUNTING LH	Bent	210.00 FL	*210.00 FL
29	1		*ABSORBER COIL SPRING LH	Serviceable	450.00 FL	*- FL
30	1		*LOWER ARM LH	Bent	452.00 FL	*452.00 FL
31	1		*LOWER ARM BALL JOINT LH	Bent	195.00 FL	*195.00 FL
32	1		*KNUCKLE ARM LH	Bent	427.00 FL	*427.00 FL
33	1		*WHEEL HUB LH	Bent	235.00 FL	*235.00 FL
34	1		*DISC ROTOR LH	Serviceable	366.00 FL	*- FL
35	1		*BRAKE PAD LH	Serviceable	145.00 FL	*- FL
36	2		*FRONT SPORT RIM RH / LH	Dented	840.00 FS	*560.00 FS
37	1		*FRONT TYRE 205/55/R16 RH / LH (\$250.00) (80%)	N/S Punctured	640.00 FS	*200.00 FS
38	8		*L GEAR BOX TRANSMISSION FLUID	Necessary	240.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,385.00	12,153.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,416.25	2,828.45
Total Parts (\$\$)	14,968.75	9,325.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,500.00	700.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,500.00	900.00
3	WIRING CHARGES	New	80.00	20.00
4	REMOVE / REFIX UNDERCARRIAGE	New	500.00	320.00
5	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	300.00	30.00
6	WHEEL ALIGNMENT	New	180.00	60.00
7	REMOVE / REFIX FRONT QUARTER GLASS	New	150.00	0.00
8	RE-ALIGNMENT OF FRONT MEMBER	New	300.00	0.00
Gross Labour Cost (\$)			4,510.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >