### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way 51 Ubi Ave 1 #01-25 #21-01 SGX Centre 2 Paya Ubi Industrial Park Singapore 068807 Singapore 408933

Attn: Douglas Ong Chu Chong 10 Aug 2021 Date:

## **Preliminary Advice**

Insured Vehicle No : SMZ1579A

TP Vehicle No : SJY9825C : 23/07/2021 Accident Date Make : TOYOTA WISH Assignment Date : 26/07/2021

Date of Inspection : 26/07/2021 Est. Duration of Repair : 8

Inspection At : BLK 1 SIN MING INDUSTRIAL SECTOR C #01-135.

REPAIRER: A T AUTO CONSULTANT (HQ)

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,478.75 11,355.35	
Revised Amount	:S\$		
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,355.35	
Lump Sum Repair	:S\$	9,050.00	

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

(		)	The vehicle is economical for repair
(		)	The vehicle is not economical for repair
(		)	Part-by-Part repair
(	Х	)	Lump Sum repair

The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.