

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19004939/JES3Q2-1
Date: 11/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994697
Claimant Vehicle No :	SMB1443J	Insured Vehicle No :	SLX6202B
Date of Loss:	10/11/2018	Nature of Claim:	TP
		Claim No:	3117093283SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1443J		
Make & Model:	MAN NL320F (A22), 10.5 D (M)	Engine No:	50337801083774
Reg. Date:	25/07/2014 (Man. Year: 2014)	Chassis No:	WMAA22ZZ5E7002159
Colour:	Multi-colour	Odometer:	371352 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,938.00	1,238.00	700.00	36.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,938.00	1,238.00	700.00	36.12
+ Loss of Use (2.0 x S\$250.00/day) (S\$)		500.00		

(S\$)	1,738.00
Liabe Amount (50.00%) (S\$)	869.00
+ Doc/Search Fee (S\$)	7.00
Nett Liability (S\$)	876.00
Global Sum Settlement (S\$)	880.00

INSPECTION

Date of Assignment: 18/03/2019

Date Inspected: 18/03/2019

Estimated Period of Repair: 2.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: ONG HWEE JIE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR REAR PORTION RH	New	1,060.00	530.00
2	TO PUTTY & RESPRAY	New	878.00	708.00
Gross Labour Cost (S\$)			1,938.00	1,238.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >