

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007910/KPS3Q2
Date: 19/10/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SMM6396X

Date of Loss: 19/07/2021

Policy No:

Insured Vehicle No :

Nature of Claim:

SLH4761B

TP

Claim No: 9879609667SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMM6396X**

Make & Model: TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)

Reg. Date: 08/07/2019 (Man. Year: 2019)

Colour: Metallic Grey

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2NRX476879

Chassis No: MHFZ28H3400064433

Odometer: 28569 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,925.07	1,571.50	1,353.57	46.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,170.00	1,020.00	46.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,115.07	2,741.50	2,373.57	46.40
	+ Loss of Use (4.0 x S\$60.00/day) (S\$)	240.00		
	+ Doc/Search Fee (S\$)	7.45		

Nett Liability (S\$)	2,988.95
Global Sum Settlement (S\$)	2,980.00

INSPECTION

Date of Assignment: 26/07/2021

Date Inspected: 27/07/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Loh Heng (HQ)
176 Sin Ming Drive, #03-08 Sin Ming Auto Care
Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTH	Bent	1,238.00 FL	*1,040.40 FL
2	1		*SIENTA LOGO	Necessary	76.10 FL	*76.10 FL
3	1		*TOYOTA LOGO	Necessary	98.20 FL	*98.20 FL
4	1		*V LOGO	Necessary	56.30 FL	*56.30 FL
5	1		*BOOTH LOCK	Repair	329.40 FL	*- FL
6	1		*REAR BUMPER	Serviceable	345.70 FL	*- FL
7	1		*REAR BUMPER CENTRAL	Dented	265.40 FL	*195.00 FL
8	1		*END PANEL	Repair	543.80 FL	*- FL
9	1		*REVERSE SENSORS	O/S Dented	447.00 FL	*223.50 FL
10	1		*GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
11	1		*REAR BUMPER FOG LAMP	Mtg Cracked	298.90 FL	*231.20 FL
12	1		*REAR CRASH SENCOR	Cracked	121.30 FL	*121.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,880.10	2,082.00
- List Item Discount on L Items 25.00/25.00% (\$)	955.03	510.50
Total Parts (\$)	2,925.07	1,571.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW REAR ACCIDENT DAMAGED PORTION TO PANELBEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	980.00	500.00
2	TO RESPRAY +SUPPLY PAINT MATERIAL AND NECESSARY ITEMS TO THE AFFECTED PARTS	New	1,000.00	520.00
3	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIR WORK	New	120.00	120.00
4	TO RUST PROOF ALL AFFECTED PORTION AFTER REPAIR	New	90.00	30.00
Gross Labour Cost (S\$)			2,190.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >