

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007911/GPA3Q2**Date:** 28/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800085888
Claimant Vehicle No :	SLV3937U	Insured Vehicle No :	SJT938X
Date of Loss:	23/07/2021	Nature of Claim:	TP
		Claim No:	9079418291SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3937U	Engine No:	2ZR8248555
Make & Model:	TOYOTA VOXY HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800284961
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	298305 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,060.00	2,685.72	4,374.28	61.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	700.00	510.00	42.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,270.00	3,385.72	4,884.28	59.06
+ GST 7.00/7.00% (S\$)	578.90	237.00	341.90	59.06
Nett Amount (S\$)	8,848.90	3,622.72	5,226.18	59.06
+ Car Rental (4.0 x S\$82.00/day) (S\$)		328.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,952.72		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment:	26/07/2021		
Date Inspected:	27/07/2021	Inspected At:	Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEADLAMP	Broken	2,400.00 F	*1,750.00 FL
2	1		*LICENSE PLATE & CASING	Cracked	75.00 FS	*20.00 FS
3	1		*END PANEL	Repair	795.00 F	*- FL
4	1		*FRONT BUMPER	Deformed	1,800.00 F	*1,025.00 FL
5	1		*FOAM (FRONT REINFORCEMENT)	Cracked	380.00 F	*142.30 FL
6	1		*FRONT GRILLE BASE (BLACK)	Cracked	810.00 F	*597.00 FL
7	2		*BONNET HINGE (LH/RH)	Repair	100.00 F	*- FL
8	1		*REINFORCEMENT BAR	Not Necessary	640.00 F	*- FL
9	1		*CLIPS & RETAINERS	Necessary	60.00 FS	*30.00 FS
					Sub Total (\$)	7,060.00 3,564.30
					- List Item Discount on L Items 0.00/25.00% (\$)	0.00 878.58
					Total Parts (\$)	7,060.00 2,685.72

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE /ASSEMBLY OF HEADLAMP BUMPER FOAM,BONNET ,WIPER ,GRILLE AND ALL AFFECTED PARTS	New	810.00	400.00
2	SPRAY PAINT INCLUDING WASH & POLISH	New	400.00	300.00
Gross Labour Cost (S\$)			1,210.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >