

ASS. REC. BY: 6cl

AL6 ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Aliswell Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 90k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV39374 Yr Regn: 28 Dec 2017

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Voxy 1.8X cc 1797

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 298305 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 8WR8002849.61

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 27-07-21

Survey held at W/S 12:30pm

Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

Get Body Injured

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Misc (\$ _____)

Survey Fee: _____

Transportation: _____

____ S + RS ____ SI

Photos _____

Other: _____

TOTAL

Report Forwarded:

Emp. Sign / Date:

email: ben@allswellmotor.com.sg

4 Days.
put by put.
before print photos.
Gino Diaz
27/07/2021

DOA 23.07.2021

Date of survey

•

Engine No.

Ben

27.12.2027

-25%: 2635.72

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost

3385.72

1. Researcher's subjects are hence fully informed before taking part in the research. The researcher is very straightforward in the quoted parts are recommended to be re-

2. Participants are subject to confirmation

3. Third party survey on the "Prejudice" basis

4. No Negative and

5. Surveys are conducted and

6. is subject to the approval from insurance company

Accumulated 50 Points

Significance

Date: