

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007912/T1GS3Q2  
**Date:** 13/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100467070-05
<b>Claimant Vehicle No :</b>	SHC8703S	<b>Insured Vehicle No :</b>	GR8131A
Date of Loss:	23/07/2021	Nature of Claim:	TP
		Claim No:	3200830338SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC8703S</b>		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU673188
Reg. Date:	19/11/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU080583
Colour:	Blue	Odometer:	674741 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,210.24	80.00	1,130.24	93.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	1,030.00	160.00	13.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,400.24</b>	<b>1,110.00</b>	<b>1,290.24</b>	<b>53.75</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>168.02</b>	<b>77.70</b>	<b>90.32</b>	<b>53.76</b>

<b>Nett Amount (S\$)</b>	<b>2,568.26</b>	<b>1,187.70</b>	<b>1,380.56</b>	<b>53.75</b>
<b>+ Loss of Use (2.5 x S\$50.00/day) (S\$)</b>		125.00		
<b>+ Car Rental (2.5 x S\$114.95/day) (S\$)</b>		287.38		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,602.08</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,600.00</b>		

INSPECTION

Date of Assignment: 26/07/2021

Date Inspected: 26/07/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,160.00 FL	*- FL
2	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	35.60 FL	*- FL
3	1		*REAR WHEEL CAP RH (CUT)	Old Damaged	217.20 FL	*- FL
4	1		*REAR DOOR COMFORT APP STICKER	Necessary	80.00 FS	*80.00 FS
					<b>Sub Total (\$)</b>	<b>1,492.80</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>80.00</b>
						<b>282.56</b>
					<b>Total Parts (\$)</b>	<b>1,210.24</b>
						<b>80.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAY PAINTING CHARGE	New	800.00	750.00
3	TUFF COAT	New	90.00	0.00
Gross Labour Cost (\$\$)			1,190.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >