

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD	Re	ef:	CC4/ASM21007914/Apa3q2	
	8 SHENTON WAY AXA TOWERSING		Da	ate:	30/05/2022	
	ATTN:ONG KIAN T	THENG DERICK	Co	ode:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJR 2128P	Veh. Inspected		SME 6426K	
	Policy No.	GA474800	Coverage (\$)		0.00	
	Claim No.	S1M03E8O	Excess (\$)		0.00	
	Assign From		Assign Date		26/07/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA SIENTA	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MHFZ28H3800056562	Colour		BRONZE	
	Odometer	71195 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/50 R16	BRIDGESTONE		6 mm	
	L/H Front Tyre	195/50 R16	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195/50 R16	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195/50 R16	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/07/2021	Inspection Date		26/07/2021	
	Survey held at	MG SOLUTION PTE LTD	•			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				