

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21007927/BPA3Q2
Date: 15/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0003414_02
Claimant Vehicle No :	SJF3589Z	Insured Vehicle No :	SMY4663A
Date of Loss:	20/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003437

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF3589Z		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX749834
Reg. Date:	28/05/2008 (Man. Year: 2008)	Chassis No:	MR053HY9305062921
Colour:	Beige	Odometer:	90235 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,161.92	3,641.02	1,520.90	29.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	1,630.00	1,820.00	52.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,611.92	5,271.02	3,340.90	38.79
Approved Total (Overridden) (S\$)		4,200.00		

(S\$)	8,611.92	4,200.00	4,411.92	51.23
+ GST 7.00/7.00% (S\$)	602.83	294.00	308.83	51.23
Nett Amount (S\$)	9,214.75	4,494.00	4,720.75	51.23
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,501.45		
Global Sum Settlement (S\$)		5,500.00		

INSPECTION

Date of Assignment: 26/07/2021

Date Inspected: 26/07/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF3589Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	525.00 FL	*450.00 FL
2	1		*REAR BUMPER SIDE RETAINER LONG	Necessary	240.00 FL	*103.00 FL
3	1		*REAR BUMPER SIDE RETAINER SHORT	Not Necessary	120.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
5	1		*REAR TAIL LAMP RHS	Not Damaged	325.00 FL	*- FL
6	1		*REAR TAIL LAMP CLIPS	Not Damaged	40.00 FL	*- FL
7	1		*REAR TAIL LAMP PANEL RHS	Not Damaged	225.00 FL	*- FL
8	1		*REAR FENDER RHS	Dented	970.00 FL	*970.00 FL
9	1		*REAR AXLE	Dented	1,450.00 FL	*1,450.00 FL
10	1		*REAR RH SHOCKABSORBER	Bent	355.00 FL	*135.80 FL
11	1		*REAR RH WHEEL BEARING	Necessary	258.00 FL	*258.00 FL
12	1		*REAR DOOR RH	Bent	959.00 FL	*959.00 FL
13	1		*REAR DOOR PROTECTOR RH	Cut	98.90 FL	*98.90 FL
14	1		*REAR RH RIM	Cut	700.00 FS	*300.00 FS
15	1		*REAR RH TYRE	Not Damaged	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,565.90	4,754.70
- List Item Discount on L Items 25.00/25.00% (\$)	1,403.98	1,113.68
Total Parts (\$)	5,161.92	3,641.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,CUT ,WELD REMOVE AND REPLACING ABOVE PARTS	New	1,200.00	600.00
2	TO RESPRAY PAINTING ON THE AFFECTED AREA	New	1,000.00	600.00
3	TO CHECKING REAR WIRING	New	100.00	0.00
4	TO RESPRAY UNDERCOATING	New	150.00	40.00
5	TO REMOVE ,REFIX CUSHION AND INNER TRIM	New	150.00	0.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	250.00	120.00
7	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	60.00
8	TO REMOVE AND REFIT UNDERCARRIAGE	New	250.00	150.00
9	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
10	BALANCEING OF REAR RH RIM	New	100.00	0.00
Gross Labour Cost (S\$)			3,450.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >