

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21007930/VVF3E2

Date: 02/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100271738
Claimant Vehicle No : FBJ1600K Insured Vehicle No : SKP182T
Date of Loss: 22/07/2021 Nature of Claim: TP Claim No: 7317811161SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ1600K**
Make & Model: HONDA MSX125, 125cc Engine No: JC61E2006395
Reg. Date: 21/01/2014 (Man. Year: 2013) Chassis No: MLHJC61A4D5003897
Colour: Red Odometer: 60426 km
Engine Capacity: 125 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70/12 Rear Tyre Size: 130/70/12
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/07/2021
Date Inspected: 27/07/2021 Inspected At: Equator Brotherhood (HQ)
25 kaki bukit rd 4 #03-79 synergy @ kb
Singapore 417800
Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$4,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK GARNISH	Cut	0.00 F	*- F
3	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
4	1		*FRONT HEADLAMP BRACKET	Cut	0.00 F	*- F
5	1		*FRONT WING MIRROR RH	Repair	0.00 F	*- F
6	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F
7	1		*HANDLE BAR	Bent	0.00 F	*- F
8	1		*HANDLE BAR GRIP	Cut	0.00 F	*- F
9	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
10	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
11	1		*SIDE FAIRING	Cut	0.00 F	*- F
12	1		*FRONT FOOT REST RH	Cut	0.00 F	*- F
13	1		*REAR FOOT REST RH	Cut	0.00 F	*- F
14	1		*REAR BOX	Cut	0.00 F	*- F
15	1		*FRONT NUMBER PLATE	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >