

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21007934/ETF3E2

Date: 24/08/2021

REFERENCE

Insured/Claimant:	SUBRAMANIAM MOHANAMOOTHY	Policy No:	1800022844	
Date of Loss:	26/07/2021	Nature of Claim:	OD	Claim No: 5632061369SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU3382Z	Engine No:	G4FGHH692039
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFZ411MJ5761845
Reg. Date:	21/03/2018 (Man. Year: 2017)	Odometer:	68725 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$71,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Roadstone 4 mm	Rear Left Side:	Roadstone 4 mm
Front Right Side:	Roadstone 4 mm	Rear Right Side:	Roadstone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,667.00	5,541.80	4,125.20	42.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	5,610.00	2,270.00	28.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,547.00	11,151.80	6,395.20	36.45
+ GST 7.00/7.00% (S\$)	1,228.29	780.63	447.66	36.45
Nett Amount (S\$)	18,775.29	11,932.43	6,842.86	36.45

INSPECTION

Date of Assignment:	26/07/2021	
Date Inspected:	27/07/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*SUNDRY	Repeated	20.00 FS	-
3	1		*NEW K3 METAL STREAM MST	Broken	1,177.00 FS	*1,177.00 FS
4	1		*PANEL ASSY-FRONT DOOR, RH	Dented	1,542.00 F	*1,542.00 FL
5	1		*HINGE ASSY-DOOR UPPER, RH	Not Necessary	26.00 F	*- FL
6	1		*HINGE ASSY-REAR DOOR UPPER, RH	Not Necessary	33.00 F	*- FL
7	1		*PANEL ASSY-REAR DOOR, RH	Dented	1,361.00 F	*1,361.00 FL
8	1		*PANEL ASSY-QUARTER OUTER, RH	Dented	1,213.00 F	*1,213.00 FL
9	1		*HANDLE ASSY-DOOR OUTSIDE	Cut	214.00 F	*214.00 FL
10	1		*COVER-FR DR O/S HDL, DRIVER	Cut	22.00 F	*22.00 FL
11	1		*STRIKER ASSY-DR	Not Necessary	16.00 F	*- FL
12	1		*BASE ASSY-FR DR O/S HANDLE RH	Not Necessary	52.00 F	*- FL
13	1		*LATCH ASSY-FRONT DOOR, RH	Not Necessary	253.00 F	*- FL
14	1		*W/STRIP ASSY-RR DR BELT O/S RH	Not Necessary	89.00 F	*- FL
15	1		*GLASS-REAR DOOR FIXED, RH	Not Necessary	91.00 F	*- FL
16	1		*BLACK TAPE-FR DR FRAME UPR, RH	Necessary	13.00 F	*13.00 FL
17	1		*BLACK TAPE-FR DR RR, RH	Necessary	12.00 F	*12.00 FL
18	1		*TAPE-RR DR FRAME BLACK RR, RH	Necessary	8.00 F	*8.00 FL
19	1		*BLACK TAPE-RR DR FRAME UPR, RH	Necessary	11.00 F	*11.00 FL
20	1		*WHEEL ASSY-ALUMINIUM	Cut	981.00 F	*981.00 FL
21	1		*HUB ASSY-RR WHEEL	Not Necessary	340.00 F	*- FL
22	1		*TORSION AXLE COMPLETE	Not Necessary	1,096.00 F	*- FL
23	1		*SHOCK ABSORBER ASSY-REAR	Not Necessary	231.00 F	*- FL
24	1		*GUARD ASSY-REAR WHEEL, RH	Not Necessary	75.00 F	*- FL
25	1		*COVER-RR BUMPER	Repair	688.00 F	*- FL
26	1		*BRACKET-RR BUMPER SIDE MTG, RH	Not Necessary	29.00 F	*- FL
27	1		*FILM-ANTI CHIPPG RH	Necessary	27.00 F	*27.00 FL
28	1		*MOULDING-REAR WINDOW GLASS	Necessary	27.00 F	*27.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,667.00	6,628.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,086.20
Total Parts (\$\$)	9,667.00	5,541.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT DOOR RH, REAR DOOR RH, SIDE SKIRT RH, REAR FENDER RH, REAR BUMPER, REAR AIRDAM	New	3,600.00	2,360.00
2	SPRAY PAINT FOR FRT DOOR RH, REAR DOOR RH, SIDE SKIRT RH, REAR FENDER RH, REAR BUMPER, REAR AIRDAM	New	2,100.00	2,100.00
3	REMOVE & INSTALL SIDE SKIRT	New	100.00	0.00
4	REMOVE & INSTALL REAR AIRDAM	New	100.00	0.00
5	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
6	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	180.00	120.00
7	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS	New	180.00	120.00
8	REMOVE & INSTALL REAR WINDSCREEN TO FACILITATE REPAIR	New	300.00	300.00
9	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
10	REMOVE & INSTALL REAR FENDER INNER TRIMS	New	300.00	80.00
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
12	APPLY SEALANT FOR ACCIDENT PORTION	New	120.00	120.00
13	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	0.00
14	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	120.00
15	TRANSFER REAR RIGHT RIM	New	30.00	30.00
16	RENEW REAR UNDER CARRIAGE	New	300.00	0.00
Gross Labour Cost (\$\$)			7,880.00	5,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >