

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21007939/KQF3E2

Date: 29/10/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993660

Date of Loss: 01/07/2021

Nature of Claim: OD

Claim No: 0522897094SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF357Y	Engine No:	27492030729390
Make & Model:	MERCEDES-BENZ C200, 1.5 AMG (A)	Chassis No:	WDD2050422R213804
Reg. Date:	20/10/2016 (Man. Year: 2016)	Odometer:	154422 km
Colour:	Metallic Light Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	245/40R18
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,525.55	33,555.60	4,969.95	12.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,020.00	2,710.00	3,310.00	54.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,545.55	36,265.60	8,279.95	18.59
- Excess (S\$)	1,700.00	1,700.00	0.00	0.00
(S\$)	42,845.55	34,565.60	8,279.95	19.33
+ GST 7.00/7.00% (S\$)	2,999.19	2,419.59	579.60	19.33
Nett Amount (S\$)	45,844.74	36,985.19	8,859.55	19.33

INSPECTION

Date of Assignment: 26/07/2021

Date Inspected: 27/07/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS (WCP)	Cracked	660.00 F	*660.00 F
2	1		*DASHBOARD ASSY (WCP)	Torn	2,495.00 F	*2,495.00 F
3	1		*STEERING AIR BAG (WCP)	Burst	1,450.00 F	*1,450.00 F
4	1		*PASSENGER AIR BAG (WCP)	Burst	1,450.00 F	*1,450.00 F
5	1		*KNEE AIR BAG (WCP)	Burst	850.00 F	*850.00 F
6	1		*AIRBAG CONTROL UNIT (WCP)	Necessary	680.00 F	*680.00 F
7	1		*AIRBAG SENSOR (WCP)	Necessary	155.00 F	*155.00 F
8	2		*FRONT SAFETY BELT-RH/LH (WCP)	Jammed	1,120.00 F	*1,120.00 F
9	2		*REAR SAFETY BELT-RH/LH (WCP)	Jammed	700.00 F	*700.00 F
10	1		*BONNET (WCP)	Bent	1,200.00 F	*1,200.00 F
11	1		*BONNET CENTRE LOGO (WCP)	Necessary	58.00 F	*58.00 F
12	1		*BONNET INSULATOR (WCP)	Deformed	185.00 F	*185.00 F
13	1		*BONNET STOPPER-LH (WCP)	Serviceable	12.00 F	*- F
14	2		*BONNET HINGE-RH/LH (WCP)	Distorted	270.00 F	*270.00 F
15	2		*BONNET ABSORBER-RH/LH (WCP)	Punctured	180.00 F	*180.00 F
16	2		*BONNET ACTUATOR-RH/LH (WCP)	Serviceable	384.00 F	*- F
17	2		*BONNET SPRING-RH/LH (WCP)	Serviceable	56.00 F	*- F
18	1		*BONNET CENTER LOCK (WCP)	Bent	68.00 F	*68.00 F
19	1		*BONNET LOCK-LH (WCP)	Repair	62.00 F	*- F
20	1		*BONNET LOCK SWITCH-LH (WCP)	Serviceable	45.00 F	*- F
21	1		*BONNET CABLE-FRONT (WCP)	Serviceable	58.00 F	*- F
22	1		*BONNET CABLE-REAR (WCP)	Serviceable	48.00 F	*- F
23	1		*SUPPORT PANEL (WCP)	Buckled	585.00 F	*585.00 F
24	1		*SUPPORT PANEL TOP GARNISH (WCP)	Serviceable	48.00 F	*- F
25	1		*SUPPORT PANEL STRIKER (WCP)	Bent	48.00 F	*48.00 F
26	1		*BRACE PANEL (WCP)	Repair	48.00 F	*- F
27	2		*HEADLAMP ASSY-RH/LH (WCP)	Broken	5,160.00 F	*5,160.00 F
28	1		*HEADLAMP BRACKET-LH (WCP)	Distorted	65.00 F	*65.00 F
29	1		*HEADLAMP CONTROL UNIT - LH (WCP)	Cracked	520.00 F	*520.00 F
30	1		*FRONT GRILLE (WCP)	Cracked	128.00 F	*128.00 F
31	1		*FRONT GRILLE BEAM MOULDING (WCP) (4PCS)	Dented / Cracked (3Pcs only)	312.00 F	*234.00 F
32	1		*FRONT GRILLE CENTRE LOGO (WCP)	Missing	98.00 F	*98.00 F
33	1		*FRONT GRILLE CENTRE LOGO BASE (WCP)	Missing	65.00 F	*65.00 F
34	1		*FRONT GRILLE SUPPORT (WCP)	Distorted / Cracked	195.00 F	*195.00 F
35	1		*FRONT GRILLE INNER GARNISH (WCP)	Cracked	95.00 F	*95.00 F
36	1		*FRONT BUMPER (WCP)	Torn	1,080.00 F	*1,080.00 F
37	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	350.00 F	*350.00 F
38	1		*FRONT BUMPER BRACKET - LH (WCP)	Bent	230.00 F	*230.00 F
39	2		*FRONT BUMPER INNER CARRIER - RH / LH (WCP)	Cracked	150.00 F	*150.00 F
40	1		*FRONT BUMPER STRUT - LH (WCP)	Bent	42.00 F	*42.00 F
41	1		*FRONT BUMPER RADAR SENSOR (WCP)	Cracked	780.00 F	*780.00 F
42	1		*FRONT BUMPER SPONGE (WCP)	Missing	125.00 F	*125.00 F
43	1		*FRONT BUMPER CENTRE GRILLE (WCP)	Missing	108.00 F	*108.00 F
44	1		*FRONT BUMPER LOWER INNER FRAME (WCP)	Cracked	105.00 F	*105.00 F
45	1		*FRONT BUMPER SIDE RETAINER - LH (WCP)	Cracked	24.00 F	*24.00 F
46	1		*FRONT BUMPER SENSOR (WCP) (6PCS)	Shorted(5Pcs Only)	828.00 F	*690.00 F
47	6		*FRONT BUMPER SENSOR SEAL (WCP)	Necessary	48.00 F	*48.00 F
48	1		*FRONT BUMPER SENSOR CABLE (WCP)	Torn	130.00 F	*130.00 F
49	1		*FRONT BUMPER TOW COVER (WCP)	Missing	35.00 F	*35.00 F
50	2		*FRONT BUMPER FOG LAMP COVER - RH / LH (WCP)	Dented / Distorted	140.00 F	*140.00 F
51	2		*FRONT BUMPER FOG LAMP COVER BASE - RH / LH (WCP)	Cracked	136.00 F	*136.00 F
52	1		*FRONT BUMPER LOWER CHROME - CENTRE (WCP)	Cracked	205.00 F	*205.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	2		*REAR BUMPER LOWER CHROME - RH / LH (WCP)	O/S Missing / N/S Necessary	304.00 F	*304.00 F
54	1		*FRONT BUMPER UNDER COVER (WCP)	Cracked	168.00 F	*168.00 F
55	1		*FRONT BUMPER LOWER SPOILER (WCP)	No such part	120.00 F	*- F
56	1		*FRONT NUMBER PLATE GARNISH (WCP)	Cracked	98.00 F	*98.00 F
57	2		*HORN - RH / LH (WCP)	Serviceable	2,970.00 F	*- F
58	1		*FRONT FENDER - LH (WCP)	Bent	555.00 F	*555.00 F
59	1		*FRONT FENDER INNER SHIELD (FRONT) - RH / LH (WCP) (2PCS)	Cracked (1Pc Only)	184.00 F	*92.00 F
60	1		*WASHER TANK (WCP)	Serviceable	98.00 F	*- F
61	1		*WASHER TANK HOSE (WCP)	Punctured	53.00 F	*53.00 F
62	1		*AIR-CON CONDENSER (WCP)	Punctured	950.00 F	*950.00 F
63	1		*RADIATOR ASSY (INNER) (WCP)	Bent	750.00 F	*750.00 F
64	1		*RADIATOR ASSY (OUTER) (WCP)	Bent	680.00 F	*680.00 F
65	1		*RADIATOR FAN MOTOR ASSY (WCP)	Cracked	1,050.00 F	*1,050.00 F
66	1		*RADIATOR TOP COVER (WCP)	Dented	55.00 F	*55.00 F
67	1		*RADIATOR LOWER COVER (WCP)	Cracked	122.00 F	*122.00 F
68	2		*AIR DUCT - RH / LH (WCP)	Cracked	136.00 F	*136.00 F
69	1		*ERP BRACKET	Necessary	35.00 FS	*28.00 FS
70	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
71	2		*RADIATOR COOLANT (TIN)	Necessary	80.00 FS	*50.00 FS
72	1		*POWER STEERING FLUID (TIN)	Necessary	92.00 FS	*50.00 FS
73	1		*FRONT GRILLE BEAM (WCP)	Cracked	185.00 F	*185.00 F
74	2		*SUPPORT PANEL BRACKET - RH/LH (WCP) (Supplementary)	Cracked	336.00 F	*336.00 F
75	1		*FRONT BUMPER BRACKET - RH (WCP) (Supplementary)	Bent	230.00 F	*230.00 F
76	1		*FRONT BUMPER STRUT - RH (WCP) (Supplementary)	Bent	42.00 F	*42.00 F
77	2		*HORN BRACKETS - RH/LH (WCP) (Supplementary)	Bent	90.00 F	*90.00 F
78	1		*FRONT FENDER - RH (WCP) (Supplementary)	Buckled	555.00 F	*555.00 F
79	2		*RADIATOR TOP CLIPS - RH/LH (WCP) (Supplementary)	Necessary	24.00 F	*24.00 F
80	1		*RADIATOR VENT LINE (WCP) (Supplementary)	Cracked	85.00 F	*85.00 F
81	1		*RADIATOR VENT LINE JOINT (WCP) (Supplementary)	Cracked	112.00 F	*112.00 F
82	1		*RADIATOR LOWER SUPPORT - RH (WCP) (Supplementary)	Distorted	28.00 F	*28.00 F
83	10		*BONNET INSULATOR CLIPS	Necessary	71.50 FS	*30.00 FS
84	1		*SUPPORT PANEL TOP GARNISH CLIPS (6PCS)	Necessary	33.00 FS	*20.00 FS
85	1		*FRONT BUMPER CLIPS (15PCS)	Necessary	90.75 FS	*50.00 FS
86	20		*FRONT FENDER INNER SHIELD CLIPS - LH	Necessary	143.00 FS	*50.00 FS
87	1		*ROOF TOP MOULDING - LH (WCP) (Supplementary)	Bent	155.00 F	*155.00 F
88	1		*FRONT BUMPER TOP GARNISH (WCP) (Supplementary)	Torn	78.00 F	*78.00 F
89	1		*FRONT BUMPER PRESSURE SENSOR (WCP) (Supplementary)	Cracked	165.00 F	*165.00 F
90	1		*RADIATOR TOP BEARING - LH (WCP) (Supplementary)	Missing	26.00 F	*26.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	35,078.25	30,534.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	3,447.30	3,021.60
Total Parts (\$\$)	38,525.55	33,555.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER AND REFILL AIR-CON GAS	New	150.00	100.00
2	TO REMOVE AND REFIT RADIATOR ASSY AND PRESSURE OF AIR	New	100.00	50.00
3	TO REMOVE AND REFIT DASHBOARD, METER AND GROVE BOX COMPARTMENT TO FACILITATES THE REPAIR	New	580.00	280.00
4	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	150.00	120.00
5	TO DISMANTLE AND REFIT CONSOLE BOX TO ENABLE REPLACE AIRBAG CONTROL UNIT	New	280.00	80.00
6	TO REMOVE AND REPLACE STEERING AIRBAG, PASSENGER AIRBAG, KNEE AIRBAG, FRONT AND REAR SAFETY BELT, AIRBAG CONTROL UNIT AND AIRBAG SENSOR	New	800.00	300.00
7	TO CHECK RECTIFY WIRING SYSTEM	New	80.00	30.00
8	TO PANEL BEAT AND STRAIGHTEN BOTH SIDE FRONT FENDER INNER PANEL, FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,800.00	700.00
9	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,500.00	800.00
10	TO RE-PROGRAM AND RESET ALL CONTROL MODULE FAULTY CODE	New	580.00	250.00
Gross Labour Cost (S\$)			6,020.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >