

# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543 Email: mirage1195@gmail.com

## ACCIDENT VEHICLE INSPECTION REPORT

Report no : 136M0421.PH

Vehicle no : SFM8121S

### 1 REFERENCE

Date of inspection : 20 April 2021

Requested by : Lim Kim Chai  
Blk 289A Bukit Batok St 25

#06-210

Singapore 650289

Type of survey : Independent

Repairer : Paul Hoe Batteries & Motor Services

Blk 1 Kaki Bukit Ave 6, #01-109 AutoBay @ Kaki Bukit, Singapore 417883

Date of accident : 10 April 2021

### 2 VEHICLE DATA

Make/model : TOYOTA HARRIER PREMIUM 2.0 A

Chassis no : ZSU600063257

Engine no : 3ZRB674142

Date of registration : 12 January 2016 COE Expiry Date: 11 January 2026

Engine capacity : 1986 cc

Odometer reading : 102428 km

Colour : Black

### 3 STATIC CONDITION CHECK

Steering : Affected

Foot brakes : Serviceable

Hand brakes : Serviceable

Paintwork : Good

General Condition : Good

### 4 TIRE CONDITION CHECK

Front tread : 5 mm/Pirelli

Rear tread : 5 mm/Pirelli

RH/MAKE

LH/MAKE

SIZE

SIZE

235/55R18

235/55R18

### 5 BRIEF DESCRIPTION OF DAMAGE

Front bumper sides grazed/squashed/deformed, front LH fender bent, LH headlamp scraped/casing cracked, front left hand suspension and undercarriage damaged, etc. Please see para. 8 of this report for more details.

### 6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

### 7 RECOMMENDATION

Cost of repairs : **\$8,300.00** (lump sum)

Estimated no of days : **Five (5)**

**8 ASSESSMENT OF DAMAGE AND COSTS**

Report no: 136M0421.PH  
 Vehicle no: SFM8121S

**A SPARE PARTS**

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>
Front bumper	1	sides grazed/squashed/deformed	627.45	627.45
Front bumper side retainer	2	necessary	342.50	342.50
Front bumper inner side foam, LH/RH	2	mounting knobs broken	363.80	363.80
Front bumper centre foam	1	cracked	191.60	191.60
Front bumper lower spoiler	1	scraped/deformed	571.70	571.70
Front bumper centre grille	1	warped/legs bent	371.25	371.25
LH front knuckle arm	1	bent/distorted	571.45	571.45
LH front knuckle arm bearing	1	cone broken	371.25	371.25
LH front lower arm	1	bent	381.90	381.90
LH front shock absorber	1	bent	581.10	581.10
LH front drive shaft	1	bent/screw tread damaged	2,721.45	2,721.45
LH front stabiliser link	1	bent	271.75	271.75
LH headlamp assy	1	scraped/casing cracked	2,821.10	2,821.10
LH headlamp lower bracket	1	bent	171.45	171.45
LH front fender	1	to repair	971.25	0.00
		Subtotal of the above	11,331.00	10,359.75
		Discount 25% / 25%	2,832.75	2,589.94
<u>(Special nett)</u>		Subtotal 1:	8,498.25	7,769.81
LH front sport rim	1	abraded/scraped	750.00	750.00
LH front tyre	1	serviceable	305.00	0.00
Front bumper clip	10	necessary	55.00	55.00
		Subtotal 2:	1,110.00	805.00
		Total cost of parts:	9,608.25	8,574.81

**B LABOUR**

To check wiring.	40.00	30.00
To align headlamps and refocus headlamp beams to specifications.	80.00	60.00
To apply anti-rust undercoat.	120.00	60.00
Labour charges to remove and replace, to cut and weld, to panel beating affected and damaged parts.	750.00	500.00
Spray painting charges to paint the front bumper, front fender and necessary areas.	750.00	500.00
To conduct 4-wheel computerised alignment to realign wheels.	90.00	90.00
To remove and replace damaged front right hand suspension parts.	600.00	450.00
Total cost of labour:	2,430.00	1,690.00
Total cost of repair:	12,038.25	10,264.81

Report no: 136M0421.PH

Vehicle no: SFM8121S

**9 CONCLUSION**

The revised or adjusted cost of repairs to restore the vehicle is

\$10,264.81

(a) However, the recommended cost of repair based on lump sum basis would be

**\$8,300.00**

(b) The number of days taken to complete the repairs are

**Five (5)**

(1<sup>st</sup> re-inspection conducted on 20 April 2021)

(Post Repair Inspection conducted on 23 April 2021)

*The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.*

**Note: Lump Sum Repair Basis**

*This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.*

Yours faithfully



Liaw Leong San

Licensed Automotive Appraiser

Dated: 1 June 2021

# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543 Email: mirage1195@gmail.com

Lim Kim Chai  
Blk 289A Bukit Batok St 25  
#06-210  
Singapore 650289

Invoice no:	POS0136/21
Date:	1 June 2021
Report no:	136M0421.PH
Vehicle :	SFM8121S

## INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			779.00
SGD(\$): Seven Hundred and Seventy-nine only			Payable Amount:	779.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



.....  
Authorised Signature